



**Nantucket Elementary School
30 Surfside Road
Nantucket, Massachusetts**

AHERA INSPECTION REPORT/MANAGEMENT PLAN

July 2023

PREPARED FOR:

Nantucket Public Schools
12 Surfside Road
Nantucket, Massachusetts
Attn: Ms. Diane O'Neil

PREPARED BY:

The Vertex Companies, LLC
400 Libbey Parkway
Weymouth, MA 02189
781-952-6000

VERTEX Project No: 89066

Table of Contents

- Section 1 - Introduction
 - Bulk Sampling Methodology
 - Updated Homogeneous Area Hazard Assessment
- Section 2 - Response Action Determination
- Section 3 - Updated Recommended Response Actions
- Section 4 - Recordkeeping Requirements and Recommendations
- Section 5 - Estimated Resources Needed to Complete Response Actions
- Section 6 - Estimated Resources Required for the Abatement of the Identified ACMs
- Section 7 - Operations and Maintenance

Appendices

- Appendix A - Locations of the ACMs and Updated Conditions
- Appendix B - Estimated Costs to Needed to Complete the Response Actions
- Appendix C - Estimated Costs to for Abatement of the Identified ACMs
- Appendix D - Personnel Certifications
- Appendix E - Designated Person Assurances
- Appendix F - Six-Month Surveillance
- Appendix G - Schematics

Introduction

The Vertex Companies, LLC (VERTEX) conducted a 3-Year Reinspection between June 29th, 2023 as required by the 40 CFR 763 Asbestos Hazard Emergency Response Act (AHERA) at the Nantucket Elementary School located at 30 Surfside Road in Nantucket, Massachusetts. The AHERA regulation requires that each Local Education Agency (LEA) retain a certified/accredited Asbestos Inspector to conduct an initial inspection of all friable and non-friable known or assumed asbestos-containing materials (ACMs) in each school building that they lease, own, or otherwise uses as a school building. The AHERA re-inspection is to be performed by an accredited inspector at least once every three years from the time of implementation of the original management plan. In addition, the LEA is responsible for conducting Six-Month Periodic Surveillance Inspections as required to effectively manage the identified ACBMs in place at the school.

The Nantucket Public School District may utilize the information obtained from the AHERA inspection to effectively manage the ACBMs identified at the Nantucket Elementary School.

SECTION 1
INSPECTION REPORT

Section 1
Inspection Report

Inspection Protocol

Massachusetts Department of Labor Standards (DLS) Certified Asbestos Inspector, Jason Mohre (AI#000262) performed the AHERA inspection. The Management Plan was developed by Massachusetts DLS Certified Asbestos Management Planner, Jason Mohre (AP#000080). The purpose of the inspection was to identify friable and non-friable ACBMs and perform a hazard assessment. As required by the AHERA regulation, the inspection survey procedures must include a visual inspection and assessment of the condition of all known locations of friable and non-friable ACBMs. It should be noted that under the AHERA regulations only ACBMs are inspected within the school building, other asbestos containing materials (ACMs) may be associated with the school that do not fall under AHERA ACBM definition. Examples of materials which have been found to contain asbestos include but are not limited to exterior window caulking, window glazing, and roofing material. Prior to school renovations any suspect materials not sampled or listed within the school's AMP, must be tested prior to disturbance. Furthermore, VERTEX recommends an Asbestos Containing Materials (ACMs) Survey be conducted prior to any renovation activities to comply with the Environmental Protection Agency (EPA) Title 40 CFR Part 61, National Emissions Standards for Hazardous Air Pollutants (NESHAPs) and the Massachusetts Department of Environmental Protection Regulations. Documentation for subsequent surveys not related to AHERA should be included in the overall Management Plan.

Assessment of potential asbestos hazards is subject to each individual inspector's judgment, and as a result, hazard assessments may vary.

Furthermore, the LEA Designated Person should assume that potential asbestos-containing pipe and fitting insulation or other ACBMs may be located under flooring materials, behind walls and/or ceilings not accessible. Any renovation/demolition work that may penetrate these areas should be inspected prior to disturbance.

All available documentation of asbestos abatement projects, which have occurred since the initial AHERA inspection should be included with the Management Plan for the school.

The previous 3-Year Reinspections was conducted by VERTEX in July 2020 and Rhode Island Analytical (RI Analytical) in October 2017. Based on review of the past RI Analytical 3-Year Reinspection Report, VERTEX noted that a majority of the ACBMs had been assumed and laboratory data was not included within the October 2017 report and current Asbestos Management Plan for the school.

Appendix F contains Certification Page for the Inspector and Management Planner involved with the inspection of the school.

Locations of the identified ACBMs with quantities observed, conditions assessed, homogeneous hazard assessment are presented in Appendix A of this report.

Section 1
Inspection Report (continued)

Bulk Sampling Methodology

Bulk samples were not collected during the current re-inspection activities in June 2023. However, VERTEX had collected and analyzed the following bulk samples of suspect homogeneous materials within the facility during an AHERA inspection conducted in July 2020. Please refer to Table 1 below for a summary of the bulk samples collected and analyzed

30 Surfside Road
Sample Locations and Results
Table I

Sample Number	Sample Description	Sample Location	Asbestos Content
B-707-01A	Yellow Carpet Adhesive	A-3	None Detected
B-707-01B	Yellow Carpet Adhesive	D-Well	None Detected
B-707-01C	Yellow Carpet Adhesive	Library	None Detected
B-707-02A	12" Beige Floor Tile	C-Cluster Area	3 % Chrysotile
B-707-02B	12" Beige Floor Tile	A-Cluster Area	Positive Stop
B-707-03A	Black Floor Tile Mastic	C-Cluster Area	10 % Chrysotile
B-707-03B	Black Floor Tile Mastic	A-Cluster Area	Positive Stop
B-707-03C	Black Floor Tile Mastic	Main Corridor	Positive Stop
B-707-03D	Black Floor Tile Mastic	Pre-K	Positive Stop
B-707-03E	Black Floor Tile Mastic	Teachers Breakroom	Positive Stop
B-707-04A	12" Gray Spec Floor Tile	D-1	None Detected
B-707-04B	12" Gray Spec Floor Tile	Cafeteria	None Detected
B-707-05A	Black Floor Tile Mastic	D-1	10 % Chrysotile
B-707-05B	Black Floor Tile Mastic	Cafeteria	Positive Stop
B-707-06A	12" Off-White Gray Spec Floor Tile	D-2	None Detected
B-707-06B	12" Off-White Gray Spec Floor Tile	E-4	None Detected
B-707-07A	Yellow Floor Tile Mastic	D-2	None Detected
B-707-07B	Yellow Floor Tile Mastic	E-4	None Detected
B-707-08A	12" Beige Spec Floor Tile	E-3	None Detected
B-707-08B	12" Beige Spec Floor Tile	E-3	None Detected
B-707-09A	Black Floor Tile Mastic	E-3	10 % Chrysotile
B-707-09B	Black Floor Tile Mastic	E-3	Positive Stop
B-707-10A	12" Gray Floor Tile	Academic Closet D	None Detected
B-707-10B	12" Gray Floor Tile	Academic Closet D	None Detected
B-707-11A	Black Floor Tile Mastic	Academic Closet D	10 % Chrysotile
B-707-11B	Black Floor Tile Mastic	Academic Closet D	Positive Stop
B-707-12A	12" Red Floor Tile	Music Room 101	3 % Chrysotile
B-707-12B	12" Red Floor Tile	Music Room 101	Positive Stop
B-707-13A	Black Floor Tile Mastic	Music Room 101	10 % Chrysotile
B-707-13B	Black Floor Tile Mastic	Music Room 101	Positive Stop
B-707-14A	12" Red w/White Spec Floor Tile	D-Cluster Area	None Detected
B-707-14B	12" Red w/White Spec Floor Tile	D-Cluster Area	None Detected
B-707-15A	12" Blue Floor Tile	E-Cluster Area	None Detected
B-707-15B	12" Blue Floor Tile	E-Cluster Area	None Detected
B-707-16A	Parque Floor Adhesive	Teachers Breakroom	None Detected
B-707-16B	Parque Floor Adhesive	Teachers Breakroom	None Detected
B-707-17A	Gray w/ Blue Spec Sheet Flooring	E-9	None Detected
B-707-17B	Gray w/ Blue Spec Sheet Flooring	E-9	None Detected
B-707-18A	Yellow Sheet Flooring Adhesive	E-9	None Detected
B-707-18B	Yellow Sheet Flooring Adhesive	E-9	None Detected

30 Surfside Road
Sample Locations and Results
Table I (Continued)

Sample Number	Sample Description	Sample Location	Asbestos Content
B-707-19A	Faux Wood Sheet Flooring	E-14	None Detected
B-707-19B	Faux Wood Sheet Flooring	E-10	None Detected
B-707-20A	Yellow/White Sheet Flooring Adhesive	E-14	None Detected
B-707-20B	Yellow/White Sheet Flooring Adhesive	E-10	None Detected
B-707-21A	Beige Ramp Tread	Library	None Detected
B-707-21B	Beige Ramp Tread	Library	None Detected
B-707-22A	Yellow Ramp Tread Adhesive	Library	None Detected
B-707-22B	Yellow Ramp Tread Adhesive	Library	None Detected
B-707-23A	Red Floor Leveler	Library Hall	None Detected
B-707-23B	Red Floor Leveler	Library Hall	None Detected
B-707-24A	Tan Covebase	Pre-K	None Detected
B-707-24B	Tan Covebase	Pre-K	None Detected
B-707-25A	Brown Covebase Adhesive	Pre-K	None Detected
B-707-25B	Brown Covebase Adhesive	Pre-K	None Detected
B-707-26A	Black Covebase	C-3	None Detected
B-707-26B	Black Covebase	B-1	None Detected
B-707-27A	Blue Covebase	Gym	None Detected
B-707-27B	Blue Covebase	Gym	None Detected
B-707-28A	Gray Covebase	D-Cluster Area	None Detected
B-707-28B	Gray Covebase	E-Cluster Area	None Detected
B-707-29A	Yellow Covebase Adhesive	C-3	None Detected
B-707-29B	Yellow Covebase Adhesive	Gym	None Detected
B-707-29C	Yellow Covebase Adhesive	D-Cluster Area	None Detected
B-707-30A	Ceramic Wall Tile Adhesive (Yellow)	D-2	None Detected
B-707-30B	Ceramic Wall Tile Adhesive (Yellow)	D-3	None Detected
B-707-31A	Ceramic Wall Tile Grout (White)	D-2	None Detected
B-707-31B	Ceramic Wall Tile Grout (White)	D-3	None Detected
B-707-32A	Black Sink Mastic	Pre-K	5 % Chrysotile
B-707-32B	Black Sink Mastic	B-Cluster Area	Positive Stop
B-707-32C	Black Sink Mastic	E-7	Positive Stop
B-707-33A	Yellow Duct Sealant	Mechanical Penthouse	3 % Chrysotile
B-707-33B	Yellow Duct Sealant	Mechanical Penthouse	Positive Stop
B-707-34A	Green Duct Sealant	Kitchen	None Detected
B-707-34B	Green Duct Sealant	Kitchen	None Detected
B-707-35A	Gray Duct Sealant	Music Room 101	None Detected
B-707-35B	Gray Duct Sealant	Music Room 101	None Detected
B-707-36A	Off-White Building Caulking	Gym	3 % Chrysotile
B-707-36B	Off-White Building Caulking	A-Cluster Area	Positive Stop
B-707-36C	Off-White Building Caulking	C-Cluster Area	Positive Stop

30 Surfside Road
Sample Locations and Results
Table I (Continued)

Sample Number	Sample Description	Sample Location	Asbestos Content
B-707-37A	Off-White Interior Door Caulking	Nurse Office	3 % Chrysotile
B-707-37B	Off-White Interior Door Caulking	Pre-K	Positive Stop
B-707-37C	Off-White Interior Door Caulking	C-3	Positive Stop
B-707-38A	Drywall	Pre-K	None Detected
B-707-38B	Drywall	A-2	None Detected
B-707-38C	Drywall	B-5	None Detected
B-707-38D	Drywall	C-6	None Detected
B-707-38E	Drywall	E-6	None Detected
B-707-38F	Drywall	Academic Closet D	None Detected
B-707-39A	Joint Compound	Lobby	None Detected
B-707-39B	Joint Compound	B-5	None Detected
B-707-39C	Joint Compound	A-2	None Detected
B-707-39D	Joint Compound	C-6	None Detected
B-707-39E	Joint Compound	D-Cluster Area	None Detected
B-707-39F	Joint Compound	E-6	None Detected
B-707-39G	Joint Compound	Cafeteria	None Detected
B-707-39H	Joint Compound	Library	None Detected
B-707-39I	Joint Compound	Kitchen	None Detected
B-707-40A	Pipe Fitting Insulation	Pre-K	None Detected
B-707-40B	Pipe Fitting Insulation	Pre-K	None Detected
B-707-40C	Pipe Fitting Insulation	Main Corridor	None Detected
B-707-40D	Pipe Fitting Insulation	A-3	None Detected
B-707-40E	Pipe Fitting Insulation	B-3	None Detected
B-707-40F	Pipe Fitting Insulation	C-4	None Detected
B-707-40G	Pipe Fitting Insulation	Library Hall	None Detected
B-707-40H	Pipe Fitting Insulation	118-Storage	None Detected
B-707-40I	Pipe Fitting Insulation	Mechanical Penthouse	None Detected
B-707-41A	2' x 2' Ceiling Tile (Fissure/Dot)	Kitchen	None Detected
B-707-41B	2' x 2' Ceiling Tile (Fissure/Dot)	Bayberry Corridor	None Detected
B-707-42A	2' x 2' Ceiling Tile (Speckled/Dot)	Main Office	None Detected
B-707-42B	2' x 2' Ceiling Tile (Speckled/Dot)	Kitchen	None Detected
B-707-43A	2' x 2' Ceiling Tile (Fissure/Dot)-Replacements	E-15	None Detected
B-707-43B	2' x 2' Ceiling Tile (Fissure/Dot)-Replacements	Bayberry Corridor	None Detected
B-707-44A	Rope Packing Material	Music Room 101	None Detected
B-707-44B	Rope Packing Material	Music Room 101	None Detected

Bold indicates representative bulk sample analyzed positive for Asbestos (>1% asbestos containing)

Positive Stop indicates representative bulk sample analyzed positive for Asbestos.

Section 1
Inspection Report (continued)

The following is a list of materials that were determined or assumed to be asbestos-containing:

12" Beige Floor Tile	12" Red Floor Tile
Black Floor Tile Mastic	Black Residual Floor Tile Mastic
Black Sink Mastic	Yellow Duct Sealant
Off-White Building Caulking	Off-White Door Caulking
Wood Flooring Materials	Pipe Fitting Insulation

The following is a list of materials that were found and determined to be non-asbestos:

Yellow Carpet Adhesive	12" Gray Spec Floor Tile
12" Off-White Gray Spec Floor Tile	12" Gray Floor Tile
12" Red w/White Spec Floor Tile	12" Off-White Tan Spec Floor Tile
12" Blue Floor Tile	Yellow Floor Tile Mastic
Wood Parque Floor Adhesive	Gray w/ Blue Spec Sheet Flooring
Faux Wood Sheet Flooring	Yellow Sheet Flooring Adhesive
White/Yellow Sheet Flooring Adhesive	Beige Ramp Tread
Yellow Ramp Tread Adhesive	Tan Covebase
Black Covebase	Gray Covebase
Brown Covebase Adhesive	Yellow Covebase Adhesive
Ceramic Wall Tile Adhesive	Ceramic Wall Tile Grout
Green Duct Sealant	Gray Duct Sealant
Drywall	Joint Compound
2' x 2 Ceiling Tile (Fissure/Dot)	2' x 2 Ceiling Tile (Fissure/Dot)-Replacements
2' x 2 Ceiling Tile (Speckled/Dot)	

VERTEX recommends an ACMs Survey be conducted prior to any renovation activities to comply with the EPA Title 40 CFR Part 61, NESHAPs and the Massachusetts Department of Environmental Protection (MassDEP) Regulations.

Section 1
Inspection Report (continued)

Hazard Assessment

Each ACBM homogeneous area is assessed to determine the asbestos hazard. Factors considered when assessing homogeneous area hazard include: the friability of the material, the condition of material including type, severity, and extent of damage, the material's potential for disturbance (including accessibility and air flow) and the material's potential for damage. From this classification, a decision tree is used to determine the appropriate response action sufficient to protect human health and environment.

The location, estimated quantities, condition and Homogenous Area Hazard Assessment Category for the identified ACBMs are presented in Appendix A. The following is homogenous area assessment for each ACBM identified.

Homogeneous Area Assessment

Homogeneous Area #1-12" Beige Floor Tile

Classification: Non-Friable Miscellaneous ACM

Asbestos-containing 12" x 12" Beige Floor Tile is generally located within the Pre-K, Cranberry Corridor, Main Corridor, Nurses Office and the A, B and C Cluster Areas at the school. Please refer to Appendix A for the locations, conditions and estimated quantities. The 12" x 12" Beige Floor Tile was observed in generally good condition, non-friable and presents a potential for damage.

Homogeneous Area #2-12" Red Floor Tile

Classification: Non-Friable Miscellaneous ACM

Asbestos-containing 12" x 12" Red Floor Tile is located within the Music Room (101) at the school. The 12" x 12" Beige Floor Tile was observed in generally good condition, non-friable and presents a potential for damage.

Homogeneous Area #3-Black Floor Tile Mastic

Classification: Non-Friable Miscellaneous ACM

Asbestos-containing Black Floor Tile Mastic is associated with 12" Beige, Red and Gray Floor Tiles at the school. Please refer to Appendix A for the locations, conditions and estimated quantities. The Black Floor Tile Mastic is generally covered, non-friable and presents a potential for damage.

Section 1
Inspection Report (continued)
Hazard Assessment

Homogeneous Area #3-Black Residual Floor Tile Mastic

Classification: Non-Friable Miscellaneous ACM

Asbestos-containing Black Residual Floor Tile Mastic is generally located throughout the school under carpet or various colored 12" Floor Tiles. Please refer to Appendix A for the locations, conditions and estimated quantities. The Black Residual Floor Tile Mastic is generally covered, non-friable and presents a potential for damage.

Homogeneous Area #4-Black Sink Mastic

Classification: Non-Friable Miscellaneous ACM

Asbestos-containing Black Sink Mastic is generally located throughout the school under the sinks with classrooms and cluster areas. Please refer to Appendix A for the locations, conditions and estimated quantities. The Black Sink Mastic is in generally condition, non-friable and presents a potential for significant damage.

Homogeneous Area #5-Yellow Duct Sealant

Classification: Non-Friable Miscellaneous ACM

Asbestos-containing Yellow Duct Sealant was identified within the Mechanical Penthouse adjacent to the Gym. The Yellow Duct Sealant is in generally condition, non-friable and presents a potential for damage.

Homogeneous Area #6-Off-White Interior Door Caulking

Classification: Non-Friable Miscellaneous ACM

Asbestos-containing Off-White Interior Door Caulking is generally located throughout the school. Please refer to Appendix A for the locations, conditions and estimated quantities. The Off-White Interior Door Caulking is in generally good condition, non-friable and presents a potential for damage.

Homogeneous Area #7-Off-White Building Caulking

Classification: Non-Friable Miscellaneous ACM

Asbestos-containing Off-White Building Caulking is generally located throughout the school. Please refer to Appendix A for the locations, conditions and estimated quantities. The Off-White Building Caulking is in generally good condition, non-friable and presents a potential for damage.

Section 1
Inspection Report (continued)
Hazard Assessment

Homogeneous Area #8– Hardwood Flooring Materials

Classification: Non-Friable Miscellaneous ACM

Assumed asbestos-containing Hardwood Flooring Materials are assumed to be located under the Gym at the school. The Hardwood Flooring Materials are covered, non-friable and presents a potential for damage. Prior to any activity that may disturb the Hardwood Flooring Materials proper sampling and analysis should be conducted.

Homogeneous Area #9– Pipe Fitting Insulation

Classification: Friable Thermal System Insulation ACM

Assumed asbestos-containing pipe fitting insulation is located at the school. Please refer to Appendix A for the locations, conditions and estimated quantities. The Pipe Fitting insulation was observed in good condition and covered, friable and presents a potential for damage. Based on current Massachusetts Department of Labor Standards (MassDLS) regulations (454 CMR 28.00) for schools subject to AHERA, all pipe fitting insulation is determined asbestos-containing until the individual fitting has been sampled and analyzed. Prior to any activity that may disturb the pipe fitting insulation proper sampling and analysis is required to be conducted.

SECTION 2

RESPONSE ACTION DETERMINATION

Section 2

Response Action Determination

The following is based on the Decision Tree for Thermal System Insulation Type ACM. The recommended response actions are determined utilizing the “decision tree” approach for Response Action Determination as outlined in EPA’s “Asbestos Hazard Emergency Response Act,” (AHERA) 40 CFR 763. Because of defined friability factors associated with surfacing and miscellaneous materials versus thermal system insulation, separate decision trees are utilized for each group of materials.

Decision Trees are used to estimate the risk associated with exposure to asbestos in a given homogeneous area, and to recommend certain response actions, which are consistent with regulatory requirements. Eight response actions are recommended for both thermal system insulation and for surfacing/miscellaneous insulation. The response section number given to each homogeneous area indicates a priority for action, the lower the number, the more serious the hazard. Most response actions call for an operations and maintenance program, assuming that this is the least burdensome method which still protects human health and environment. This does not prohibit the building owner from removal of ACM at any time, if that is the preferred response action.

Recommended response actions are based upon the material condition, disturbance, air-flow and the potential for damage. Potential response actions include the following:

1. Significantly Damaged Thermal System Insulation: **Response Action 1.** Isolate the area and restrict access to the area. ACM should be removed as soon as possible.
2. Damaged Thermal System Insulation with High Disturbance: **Response Action 2.** Continue O&M program and remove the ACM as soon as possible or reduce the potential for disturbance.
3. Damaged Thermal System Insulation with Moderate Disturbance and in the Presence of an Air Stream: **Response Action 2.** Continue with O&M Program and remove the ACM as soon as possible or reduce the potential for disturbance.
4. Damaged Thermal System Insulation with Moderate Disturbance: **Response Action 3.** Repair ACM, continue with O&M Program.
5. Damaged Thermal System Insulation with Low Disturbance and in the Presence of an Air Stream: **Response Action 4.** Repair ACM, continue with O&M Program.
6. Damaged Thermal System Insulation with Low Disturbance: **Response Action 5.** Repair ACM, continue with O&M Program.
7. Undamaged Thermal System Insulation with High Disturbance: **Response Action 6.** Continue with O&M Program and take preventative measures to reduce disturbance.
8. Undamaged Thermal System Insulation with Moderate Disturbance: **Response Action 7.** Continue with O&M Program and take preventative measure to reduce disturbance.
9. Undamaged Thermal System Insulation with Low Disturbance: **Response Action 7.** Continue with O&M Program and take preventative measure to reduce disturbance.

Section 2

Response Action Determination

The recommended response actions are determined utilizing the “decision tree” approach for Response Action Determination as outlined in EPA’s “Asbestos Hazard Emergency Response Act,” (AHERA) 40 CFR 763. Because of defined friability factors associated with surfacing and miscellaneous materials versus thermal system insulation, separate decision trees are utilized for each group of materials.

Decision Trees are used to estimate the risk associated with exposure to asbestos in a given homogeneous area, and to recommend certain response actions, which are consistent with regulatory requirements. Ten response actions are recommended for surfacing/miscellaneous insulation. The response section number given to each homogeneous area indicates a priority for action, the lower the number, the more serious the hazard. Most response actions call for an operations and maintenance program, assuming that this is the least burdensome method which still protects human health and environment. This does not prohibit the building owner from removal of ACM at any time, if that is the preferred response action.

Recommended response actions are based upon the material condition, disturbance, air-flow and the potential for damage. Potential response actions include the following:

1. Friable Surfacing or Miscellaneous ACM with Significant Damage: **Response Action 1:** Isolate the area and restrict access to the area. Remove the ACM as soon as possible.
2. Friable Surfacing or Miscellaneous ACM with Damage and a High Disturbance: **Response Action 2:** Continue with O&M Program and remove ACM as soon as possible or reduce the potential for disturbance.
3. Friable Surfacing or Miscellaneous ACM with Damage, Moderate Disturbance and in the Presence of an Air Stream: **Response Action 2:** Continue with O&M Program and remove ACM as soon as possible or reduce the potential for disturbance.
4. Friable Surfacing or Miscellaneous ACM with Damage and Moderate Disturbance: **Response Action 3:** Continue with O&M Program and schedule removal when practical and cost-effective
5. Friable Surfacing or Miscellaneous ACM with Damage, Low Disturbance and in the Presence of an Air Stream: **Response Action 4:** Continue with O&M Program and schedule removal when practical and cost-effective
6. Friable Surfacing or Miscellaneous ACM with Damage and Low Disturbance: **Response Action 5.** Continue with O&M Program and schedule removal when practical and cost-effective
7. Friable Surfacing or Miscellaneous ACM with No Damage and High Disturbance: **Response Action 6.** Take preventative measures to reduce the disturbance.
8. Friable Surfacing or Miscellaneous ACM with No Damage and Moderate Disturbance: **Response Action 7.** Take preventative measure to reduce the disturbance.
9. Friable Surfacing or Miscellaneous ACM with No Damage and Low Disturbance: **Response Action 8.** Take preventative measure to reduce the disturbance.
10. Non-Friable Surfacing or Miscellaneous ACM: **Response Action 8:** Continue with O&M until major renovation or demolition requires removal under the EPA NESHAPS, or until hazard assessment factors change.

Section 2
Response Action Determination (continued)

Advantages and Disadvantage to Abatement Alternatives

The decision trees outlined in AHERA 40 CFR 763 are used to provide the “best” alternative for the specific conditions in each homogeneous area.

Below is a discussion of the alternative approaches to asbestos management in a building.

Long Term Operation & Maintenance Program

Advantages:

- *Low initial cost for implementation
- *Good interim plan
- *An O&M program may be implemented and carried out by in house trained personnel.

Disadvantages:

- *Asbestos remains in the building
- *Condition of the asbestos must be monitored
- *Cost of training and special work procedures may be significant
- *Effectiveness may be limited where control of the building occupants is difficult

Encapsulation

Advantages:

- *Reduces the risk of release of asbestos fibers
- *Initial cost is lower than the cost of asbestos removal
- *Asbestos-containing material may still serve its initial purpose
- *Quick temporary means of repair

Disadvantages:

- *Asbestos remains in the building and encapsulant makes removal more difficult
- *Improper encapsulation may cause the material to delaminate or pull away from substrate
- *Asbestos-containing material must have an O&M program
- *Similar preparation for asbestos removal is required for encapsulation
- *Long term cost may be greater than asbestos removal is periodic reapplication of the encapsulant is required

Section 2
Response Action Determination (continued)

Enclosure

Advantages:

- *Enclosure reduces immediate exposure
- *Initial cost of enclosure is lower than the cost of asbestos removal
- *Asbestos-containing material may still serve its initial purpose
- *Quick temporary means of repair

Disadvantages:

- *Asbestos remains in place and later removal is more difficult
- *If maintenance is required of the systems insulated with asbestos, the asbestos will be exposed
- *An O&M program will have to be implemented for the asbestos-containing material
- *Similar preparation for asbestos removal is required for enclosure

Removal

Advantages

- *Asbestos-containing material is eliminated from the building
- *There is no need for an O&M plan
- *Initial cost is great, but the future costs are eliminated

Disadvantages:

- *Re-insulating, re-fireproofing, or replacement of materials may be required
- *Improper removal may raise levels of airborne fibers higher than background levels
- *The initial cost of removal is very high
- *Areas of the building involved in asbestos removal may not be occupied during removal

SECTION 3

UPDATED RECOMMENDED RESPONSE ACTIONS

Section 3

Recommended Response Actions

The recommended response actions are for all the homogenous areas found within the school. The response actions are determined utilizing the decision tree approach for Response Action Determination as described in Section 2.

Homogeneous Area #1-12" Beige Floor Tile

Response Action 8: The 12" x 12" Beige Floor Tile located within the Pre-K, Cranberry Corridor, Main Corridor, Nurses Office and the A, B and C Cluster Areas is in generally good condition. Continue Operations and Maintenance (O&M) Program and manage the material in place until major renovations or demolition requires the removal of this material, or until the hazard assessment factors change.

Homogeneous Area #2-12" Red Floor Tile

Response Action 8: The 12" x 12" Red Floor Tile located within the Music Room (101) is in generally good condition. Continue O&M Program and manage the material in place until major renovations or demolition requires the removal of this material, or until the hazard assessment factors change.

Homogeneous Area #3-Black Floor Tile Mastic

Response Action 8: The Black Floor Tile Mastic located within the Academic Closet D was observed exposed and the associated floor tile was damaged. Cover exposed mastic and properly dispose the asbestos-contaminated floor tile. Recommended completion date of the work activities: January 2024.

Response Action 8: The Black Floor Tile Mastic located under and associated with the 12" Beige and Red Floor Tiles within the remainder of the school is generally covered. Continue O&M Program and manage the material in place until major renovations or demolition requires the removal of this material, or until the hazard assessment factors change.

Section 3
Recommended Response Actions (Continued)

Homogeneous Area #4-Black Residual Floor Tile Mastic

Response Action 8: The asbestos-contaminated 12" Floor Tile overlaying Black Residual Floor Tile Mastic located within the Bayberry Corridor and Classrooms E-6 and E-7 displays minor damage. Retain an Asbestos Project Designer to prepare a Work Plan for the removal and replacement of the damaged contaminated floor tile and retain a Massachusetts certified Abatement Contractor to complete the response actions following the Work Plan. Recommended completion date of the work activities: January 2024.

Response Action 8: The remaining Black Residual Floor Tile Mastic is located under various colored 12" Floor Tile or Carpet at the school. Please refer to Appendix A for the locations and estimated quantities. Continue O&M Program and manage the material in place until major renovations or demolition requires the removal of this material, or until the hazard assessment factors change.

Homogeneous Area #5-Yellow Duct Sealant

Response Action 8: The Yellow Duct Sealant located within the Mechanical Penthouse is in generally good condition. Continue O&M Program and manage the material in place until major renovations or demolition requires the removal of this material, or until the hazard assessment factors change.

Homogeneous Area #6-Off-White Interior Door Caulking

Response Action 8: The Off-White Interior Door Caulking located throughout the school is in generally good condition. Please refer to Appendix A for the locations and estimated quantities. Continue O&M Program and manage the material in place until major renovations or demolition requires the removal of this material, or until the hazard assessment factors change.

Homogeneous Area #7-Off-White Building Caulking

Response Action 8: The Off-White Building Caulking located throughout the school is in generally good condition. Please refer to Appendix A for the locations and estimated quantities. Continue O&M Program and manage the material in place until major renovations or demolition requires the removal of this material, or until the hazard assessment factors change.

Homogeneous Area #8-Hardwood Flooring Materials

Response Action 8: The Hardwood Flooring Materials located within the Gym are assumed to be covered. The Hardwood Flooring Materials are assumed to be asbestos-containing and should be sampled prior to any disturbance. Continue O&M Program and manage the material in place until major renovations or demolition requires the removal of this material, or until the hazard assessment factors change.

Section 3
Recommended Response Actions (Continued)

Homogeneous Area #9-Pipe Fitting Insulation

Response Action 6: Assumed asbestos-containing pipe fitting insulation is located at the school. Please refer to Appendix A for the locations, conditions and estimated quantities. The Pipe Fitting insulation was observed in good condition and covered, friable and presents a potential for damage. Based on current MassDLS regulations (454 CMR 28.00) for schools subject to AHERA, all pipe fitting insulation is determined asbestos-containing until the individual fitting has been sampled and analyzed. Prior to any activity that may disturb the pipe fitting insulation proper sampling and analysis is required to be conducted. Implement O&M Program and manage the material in place until major renovations or demolition requires the removal of this material, or until the hazard assessment factors change.

SECTION 4

RECORDKEEPING REQUIREMENTS AND RECOMMENDATIONS

Section 4

Recordkeeping Requirements and Recommendations

The AHERA regulations have very specific requirement for the maintenance of records associated with the management of the identified ACBMs in the school. The following is a list of some of the key items that the LEA Designated Person must maintain as part of the package:

- Initial AHERA inspection report and Asbestos Management Plan
- Subsequent 3-year reinspection reports.
- 6-month surveillance reports.
- Documentation for minor and major fiber release episodes. This includes abatement work performed by outside contractors as well as work performed by 16 hour trained maintenance personnel no matter how small.
- Documentation for completion of response actions (i.e. clearance testing, waste shipment records, etc.). This should always include applicable training and certification documentation for the parties involved performing the work activities.
- Labeling of ACBM (friable)
- Yearly notice to parents, teachers and staff.
- Training and medical exams for 16-hour trained personnel. Although training does not require renewal. Medicals are to be performed every year. In addition, 16-hour personnel should be fit tested every six months.
- Two-hour awareness training for staff. Any new workers are required to receive this training at start of employment. Training should include specific review of ACBMs in the building their working in.

The above items are some of the key items, which need to be incorporated into the plan. The following are some recommendations are how best to maintain for easy access and review by outside parties:

- Maintain an update the three- ring binder for the school. Have a duplicated copy, one for administration office and one for the facilities office.
- Create tab sections in the binder. Each section should contain the information above. This will allow for easy review and update.
- Ensure that for every major and minor fiber release episode, that all documentation is received.
- As you updated your file, ensure the school's is updated.

Section 4
Recordkeeping Requirements and Recommendations (continued)

Also, it is also required that if outside contractors enter building perform work that they review areas where asbestos may be present that will be near their work. Have a log at the school for them to sign that they have read and understand. This will protect the school from liability and ensure outside contactors will not disturb asbestos. Finally, periodically review program internally and with your 16-hour persons to ensure compliance.

The Black Floor Tile Mastic located within the Academic Closet D was observed exposed. Cover exposed tile and properly dispose of the asbestos-contaminated floor tile. Recommended completion date of the work activities: January 2024.

The asbestos-contaminated 12" Floor Tile overlaying Black Residual Floor Tile Mastic located within the Bayberry Corridor and Classrooms E-6 and E-7 displays minor damage. Retain an Asbestos Project Designer to prepare a Work Plan for the removal and replacement of the damaged contaminated floor tile and retain a Massachusetts certified Abatement Contractor to complete the response actions following the Work Plan. Recommended completion date of the work activities: January 2024.

Based on current MassDLS regulations (454 CMR 28.00) for schools subject to AHERA, all pipe fitting insulation is determined asbestos-containing until the individual fitting has been sampled and analyzed. Prior to any activity that may disturb the pipe fitting insulation proper sampling and analysis is required to be conducted. Implement O&M Program and manage the material in place until major renovations or demolition requires the removal of this material, or until the hazard assessment factors change.

VERTEX recommends continuing the periodic cleaning schedule with properly trained staff (i.e. 2-Hour Asbestos Awareness) utilizing HEPA-vacuums. In addition, following OSHA guidance with respect to maintaining asbestos-containing floor tile.

A required six-month periodic surveillance inspection should be scheduled for January 2024.

VERTEX recommends an ACMs Survey be conducted prior to any renovation activities to comply with the EPA Title 40 CFR Part 61, NESHAPs and the Massachusetts Department of Environmental Protection Regulations.

SECTION 5

ESTIMATED RESOURCES REQUIRED TO COMPLETE THE RESPONSE ACTIONS

Section 5
Estimated Resources Required to Complete the Response Actions

This section contains the estimated resources required to complete the abatement activities of the identified damaged ACMs. These estimates will vary according to competitive bidding, accessibility, location, and condition of ACMs, phasing of work, etc. The cost estimate below does not include abatement contractor mobilization, abatement design and/or project monitoring services.

Estimated Cost to complete the Response Actions at the Nantucket Elementary School:

\$1,500.00*

Cost Estimate Worksheet can be found in Appendix B.

* The estimated cost provided above is developed from current Abatement Contractor Unit pricing. These estimates will vary according to competitive bidding, accessibility, location, and condition of ACMs, phasing of work, etc. In addition, the costs above do not include mobilization of the Abatement Contractor, Abatement Work Plan/Design, Project Monitoring and/or Clearance Testing Services for the completion of the response actions. Please refer for below unit pricing regarding costs for the Contractor Mobilization and Clearance Testing Services:

Abatement Work Plan/Design Specification = \$500-\$2,500.00
Abatement Contactor Mobilization = \$1,500.00-\$2,500.00
Project Monitoring/Clearance Testing = \$520.00-\$760.00/per shift
Transmission Electron Microcopy (TEM) Analysis = \$75.00-\$100.00/sample
Phase Contrast Microscopy (PCM) Analysis = No Charge -\$15.00/sample
Clearance Report Preparation = \$350.00-\$800.00

**The estimated cost provided above does not include costs that may be associated with two-hour asbestos awareness training, OSHA 16-hr Operations and Maintenance Training, and/or the labor to conduct the required six-month surveillance re-inspections. Please refer below for estimated costs that may be associated with the mentioned above:

2-Hour Asbestos Awareness Training = \$75/person
OSHA 16-hr Operations and Maintenance Training = \$300/person
Six-Month Periodic Surveillance Inspection = \$400/inspection

SECTION 6

ESTIMATED RESOURCES REQUIRED FOR THE ABATEMENT OF THE IDENTIFIED ACBMs

Section 6
Estimated Resources Required For Abatement of the Identified ACMs

This section contains the estimated resources required to perform the removal of identified ACMs, however EPA recommends the ACMs to be managed in place if they are not damaged. Alternative abatement costs are estimated using current Abatement Contractor Estimates. These estimates will vary per competitive bidding, accessibility, location, and condition of ACMs, phasing of work, etc. The cost estimate below is a worst-case scenario if all identified ACMs were to be removed. The cost estimate below does not include abatement contractor mobilization, abatement design and/or project monitoring services.

Estimated Cost for the Removal of ACMs from the Nantucket Elementary School:

\$591,915.00*

Cost Estimate Worksheet can be found in Appendix C.

*The estimated cost above does not include removal of potentially concealed ACMs within the interior of the school. In addition, the estimated cost provided above does not include abatement of potential ACMs on the exterior of the site building and/or beyond the AHERA inspection.

** The estimated cost provided above is developed from current Abatement Contractor Unit pricing. These estimates will vary according to competitive bidding, accessibility, location, and condition of ACMs, phasing of work, etc. In addition, the costs above do not include mobilization of the Abatement Contractor, Abatement Work Plan/Design, Project Monitoring and/or Clearance Testing Services for the completion of the response actions. Please refer for below unit pricing regarding costs for the Contractor Mobilization and Clearance Testing Services:

Abatement Work Plan/Design Specification = \$500-\$2,500.00
Abatement Contactor Mobilization = \$1,500.00-\$2,500.00
Project Monitoring/Clearance Testing = \$520.00-\$760.00/per shift
Transmission Electron Microcopy (TEM) Analysis = \$75.00-\$100.00/sample
Phase Contrast Microscopy (PCM) Analysis = No Charge -\$15.00/sample
Clearance Report Preparation = \$350.00-\$800.00

SECTION 7

OPERATIONS AND MAINTENANCE

Section 7 **Operations and Maintenance Program**

INTRODUCTION

The Nantucket Public School District has established an overall asbestos control program that is designed to minimize exposure of all occupants of the school to asbestos fibers located at the Nantucket Elementary School. This Operations and Maintenance (O&M) Plan is an integral part of the overall program. It sets guidelines for the proper in-place management of all assumed and identified asbestos-containing materials (ACMs) located in the building.

This O&M plan contains the following sections:

- A. A description of the **duties of the LEA Designated Person (DP)**.
- B. A procedure for **notifying** workers, tenants, and other visitors where ACBM are located, and stressing the importance of avoiding disturbing the ACBM in any way.
- C. The detailed description of **O&M Activities**, including:
 - 1. **Emergency procedures** for both major and minor episodes of fiber release;
 - 2. **Periodic surveillance** of ACBM, so that any changes in the condition of ACBM can be noted, assessed, and documented; and
 - 3. Detailed descriptions of **work procedures** for both general maintenance and Asbestos Associated Project Workers, which must be used so that workers can avoid or minimize fiber release when performing activities that may disturb ACBM.
- D. A list of **records** that must be kept to document O&M and abatement activities.
- E. **Training requirements** for the DP, and custodial and maintenance staff.

In general, asbestos represents a health hazard **only** if fibers are breathed into the lungs or, in rare cases, are swallowed. Asbestos-containing materials that are non-friable (i.e. cannot be easily broken or crumbled by hand pressure) are not hazardous as long as they are intact and in good condition. Because friable materials can be easily crumbled or crushed, they are more susceptible to airborne fiber release than are non-friable materials.

It is a policy of the Nantucket Public School District that untrained employees and outside contractors **DO NOT** handle, touch or otherwise disturb any material that is asbestos or suspected of containing asbestos. A properly qualified and trained individual must handle any material that is, or may contain asbestos. Non-asbestos materials have been and may be identified by the asbestos coordinator using one or more of the following criteria: (1) lab analysis, (2) results of previous lab analysis, (3) product composition labels, (4) receipts, and so forth. At no time will any employee, student, or outside contractor assume a material to be asbestos-free. An inventory of ACBMs identified from the inspection are presented in Appendix A.

Section 7
Operations and Maintenance Program (Continued)

1. DUTIES OF THE ASBESTOS MANAGEMENT PLAN DESIGNATED PERSON

The DP oversees the implementation and management of the O&M plan. Duties of the DP include (1) notifying building staff, workers, and outside contractors where ACBM is located in the building, (2) assigning workers to tasks involving work that may disturb ACBM, (3) ensuring that abatement and O&M activities are conducted by trained qualified personnel, and (4) keeping records of all asbestos-related activities at the property.

The DP must receive training related to asbestos issues (see “Training Requirements” of this plan).

2. NOTIFICATION

The DP shall ensure that building workers, outside contractors, and tenants are notified of the location, quantity, and physical condition of identified and assumed ACBM that they might disturb. Such notification shall be accomplished by written notice, by personal communication, by posting signs at entrances to mechanical areas, and/or by labeling ACBM. By informing occupants of potential hazards in their vicinity, the notification reduces the possibility that occupants will accidentally disturb ACBM. The notification must stress that persons who disturb ACBM may accidentally release asbestos fibers into the air, and that therefore everyone must avoid disturbing ACBM. This notification will assure compliance with Occupational Health and Safety Administration (OSHA) Regulation 29 CFR Part 1926.1101, which regulates asbestos exposure as it relates to construction work (including building maintenance) and with 29 CFR 1910.1001, which regulates asbestos exposure in general industry (including normal housekeeping).

If asbestos-related construction, abatement, of O&M activities is conducted, the DP shall also notify the following persons about the presence, location, and quantity of ACBM:

- A. Employees of the building, such as maintenance and custodial personnel who will work in or adjacent to areas containing ACBM:
- B. Staff who will occupy areas containing ACBM.
- C. Prospective employers applying for or bidding for work if their employees will be expected to work in or adjacent to areas containing ACBM.
- D. Multiple employers occupying a work-site in the building, any of whose employees will be performing work within or adjacent to areas containing ACBM.

Section 7
Operations and Maintenance Program (Continued)

Before conducting any work in the building that has the potential to impact ACBM, contractors will be required to sign the Contractor's Asbestos Notification and Acknowledgment Form. In addition, all contractors and contractor's employees who work on the site will be required to notify the DP of the presence, location, and quantity of newly discovered ACBM within 24 hours (or sooner if ACBM is disturbed) of the discovery. If any building materials are discovered, the asbestos content of which is unknown, the material shall be presumed to contain asbestos, until the results of sampling and analysis prove otherwise. Appropriate sampling of the material shall be conducted by a Massachusetts Department of Labor and Work Force Development Division of Labor Standards accredited asbestos inspector and analyzed at an appropriately licensed asbestos analytical laboratory.

The DP shall ensure that all required warning signs are posted during abatement and O&M activities during which the release of asbestos fibers into the air is possible. Warning signs shall demarcate all regulated areas and shall bear the following information:

DANGER
ASBESTOS
MAY CAUSE CANCER
CAUSES DAMAGE TO LUNGS
AUTHORIZED PERSONNEL ONLY
RESPIRATORS AND PROTECTIVE
CLOTHING ARE REQUIRED IN THIS AREA

Contractors and in-house personnel who remove ACBM within the site shall label all waste containers that contain ACBM waste in accordance with OSHA and EPA guidelines.

The Massachusetts Department of Environmental Protection (DEP) and the Massachusetts Division of Labor Standards (DLS) will be notified anytime work will impact any quantity of ACBM at the school.

The DP shall ensure that all previously installed ACBM that have been identified in the facility are labeled or identified by signs, as feasible. All ACBM that are friable and accessible, such as TSI located in mechanical areas or below suspended ceilings, will be labeled. Labels shall be attached to or posted in areas where employees, residents, and outside contractors who are likely to be exposed will clearly notice (such as at the entrance to mechanical rooms).

The labels shall bear the following information:

DANGER
CONTAINS ASBESTOS FIBERS
MAY CAUSE CANCER
CAUSES DAMAGE TO LUNGS
DO NOT BREATHE DUST
AVOID CREATING DUST

Posted signs may be used in lieu of labels to indicate the type and location of each ACBM.

Section 7
Operations and Maintenance Program (Continued)

3. OPERATIONS AND MAINTENANCE ACTIVITIES

Operations and maintenance activities include:

- A. Emergency procedures to be followed in the event of a major or minor episode of fiber release;
- B. Periodic surveillance of ACBM within at the school building;
- C. Work procedures associated with planned maintenance activities that may disturb ACBM. Only properly trained personnel under the control and direction of the DP shall conduct operations and maintenance activities.
- D. Periodic Cleaning Activities

A. Emergency Procedures for Fiber Release Episodes

Fiber release episodes are categorized as *major* (the falling or dislodging of more than 3 square feet or 3 linear feet of friable ACBM), or *minor* (the falling or dislodging of fewer than 3 square feet or 3 linear feet of friable ACBM)

PROCEDURE FOR MAJOR EPISODE

- 1. Restrict entry into the area.
- 2. Immediately contact the DP
- 3. Post sign to prevent anyone from entering the area except persons necessary to perform the response action.
- 4. Shut off or temporarily modify the air-handling system to prevent the fibers from being distributed to other areas in the building.
- 5. The DP shall contact an accredited designer of abatement to prepare an abatement plan that specifies the appropriate response actions.
- 6. The DP shall ensure that only a Massachusetts Certified Asbestos Abatement Contractor conducts the response actions.

Section 7
Operations and Maintenance Program (Continued)

PROCEDURE FOR MINOR EPISODE

1. Thoroughly saturate the debris using all wetting methods necessary.
2. Clean the area using wet wiping techniques followed by vacuuming with a specially equipped High Efficiency Particulate Air (HEPA) vacuum.
3. Place all debris and all contaminated cleaning supplies (mop heads, rags, etc.) into a leak tight container, such as a 6-mil thick polyethylene waste bag, and seal the container. Place the sealed container into a second 6-mil thick polyethylene bag. If labeled waste bags are not used, apply warning label to outside of each bag used.
4. Repair the area of damaged ACBM, as follows:
 - a. Use materials such as asbestos-free spackling, plaster, cement, or insulation; or
 - b. Seal the area with latex paint or an encapsulate; or
 - c. Immediately implement other appropriate response action.

B. Periodic Surveillance

Periodic surveillance of all known and assumed ACBM shall be conducted once every six months. The purpose of the regularly scheduled surveillance is to ensure that any ACBM that are damaged or that have deteriorated are detected in a timely manner. The DP shall use the information from the periodic surveillance in conjunction with ongoing reports from the periodic surveillance in conjunction with ongoing reports from service workers of changes in the condition of the ACBM to take corrective action.

The periodic surveillance consists of a visual inspection of all known and assumed ACBM. Periodic surveillance shall also include a visual and physical evaluation of ACBM in order to determine the degree of damage and to assess the likelihood of future fiber release. The area in the immediate vicinity shall also be examined for potential loose ACBM debris. The DP shall record the cause of the damage.

Only persons who have received at least the minimum asbestos-awareness training (see "Training Requirements", of this plan) shall conduct the periodic surveillance. The results of the surveillance shall be recorded on the periodic surveillance inspection form.

Section 7
Operations and Maintenance Program (Continued)

C. Work Procedures for General Maintenance Personnel

The following work practices shall be prohibited in all circumstances:

- Drilling holes in ACBM;
- Damaging ACBM while moving furniture or other objects;
- Sweeping or dusting floors, ceilings, moldings, or other surfaces in asbestos-contaminated environments;
- Using an ordinary vacuum to clean up asbestos-containing or asbestos contaminated debris (only vacuums equipped with a HEPA filter should be used);
- Removing potentially contaminated ventilation system filters without thoroughly wetting them; and
- Shaking potentially contaminated ventilation system filters.

D. Periodic Cleaning

The following is a general outline to be utilized for the properly trained personnel to conduct the periodic cleaning activities:

- Utilization of disposable rags to wet wipe of all non-porous horizontal surfaces followed by the use of a HEPA-equipped vacuum. Dry sweeping and/or dusting is not permitted to be used to clean the surfaces.
- The collected debris within the lined HEPA-equipped vacuum and disposal rags should be properly disposed of in a labeled asbestos-waste bag accompanied by a Waste Shipment Record for future disposal at a permitted facility that accepts asbestos waste.
- Document the Name of the individual conducting the work activities, location date and time of cleaning for proper recordkeeping. These records should be included within the AMP for the school.

Section 7
Operations and Maintenance Program (Continued)

4. RECORDKEEPING REQUIREMENTS

The building owner shall maintain the following documentation pertaining to ACBM in the facility:

- All data that are relied upon to demonstrate that suspect ACBM do not in fact contain asbestos.
- All data communicated and received that identify the locations and quantities of ACBM.
- All records associated with abatement projects and O&M activities. These documents shall be maintained during the term of ownership. They shall then be transferred to successive owners, in accordance with OSHA Regulation 1926.1101 (n).
- If the owner's employees conduct activities that may potentially cause them to be exposed to asbestos fibers, the owner shall keep the following additional records:
 - All employee exposure-monitoring records pursuant to OSHA Regulation 1926.1101(f).
 - All information relative to medical surveillance of employees pursuant to OSHA Regulation 1926.1101(m). Medical surveillance shall be required only if:
 1. Employees are required to conduct tasks that would result in their exposure to airborne concentrations of asbestos above the OSHA permissible exposure limit (PEL); or
 2. If employees conduct asbestos abatement tasks for more than 30 days per year.
- The owner shall maintain all employee-training records for one year beyond the employee's last date of employment.

5. TRAINING REQUIREMENTS

The extent of asbestos training for facility employees depends on the type of asbestos-related activities they will conduct. For most employees who will require training, a two-hour awareness course will be sufficient but necessary. For employees who are involved in activities where exposure to airborne asbestos fibers is likely, a more comprehensive 16-hour training course is necessary.

Section 7
Operations and Maintenance Program (Continued)

AWARENESS TRAINING

The curriculum shall include instruction in the following:

- The location, quantity, and physical condition of all ACBM located in the facility.
- Recognition of damage, deterioration, and delaminating of ACBM.
- The health effects associated with asbestos exposure, including the relationship between smoking and asbestos in producing lung cancer.
- Procedures to be implemented in the event of a minor or major episode of fiber release.
- The requirements for posting signs and affixing labels, and the meaning of the required legends for such signs and labels.

COMPREHENSIVE WORKER TRAINING

The curriculum shall include instruction in the following:

- All awareness training information described above.
- The nature of operations that could result in exposure to asbestos, and the importance of necessary protective controls and of procedures for minimizing exposure, including:
 - engineering controls
 - work practices,
 - respirators,
 - housekeeping procedures,
 - hygiene facilities,
 - protective clothing,
 - decontamination procedures,
 - emergency procedures,
 - waste disposal procedures and any necessary instruction in the use of these controls and procedures.

Section 7

Operations and Maintenance Program (Continued)

- The purpose, proper use, fitting instructions, and limitations of respirators.
- Medical surveillance program requirements
- The contents of the OSHA standard (1926.1101) regarding asbestos in construction.
- Hands-on-training in the use of respiratory protection, other personal protection measures, and work practices.

Detailed procedures for conducting small-scale, short duration abatement activities, as defined in Appendix A to Subpart E to EPA Regulation 40 CFR Part 763.

APPENDIX A

**LOCATIONS OF THE ASBESTOS CONTAINING BUILDING MATERIALS AND
UPDATED CONDITONS**

Appendix A
AHERA Inspection June 2023
Locations of the Identified Asbestos-Containing Materials
Nantucket Elementary School-30 Surfside Rd.

Location	ACM Description	Estimated Quantity	VERTEX 2020 Cond.	VERTEX 2023 Cond.	HA #
Lobby	Black Residual Mastic (Under Carpet and 12" Gray Spec Floor Tile)	1000 ft ²	C	C	5
	Interior Door Caulking	102 lf	G	G	5
Music Room (101)	12" Red Floor Tile and Mastic (Black)	400 ft ²	G	G	5
	Black Residual Mastic (Under 12" Gray Spec and 12" Off-White Gray Spec FT)	50 ft ²	G	G	5
	Piping Fitting Insulation	4 Units	NA	G	5
	Interior Door Caulking	34 lf	C	G	5
Main Office	Interior Door Caulking	17 lf	G	G	5
Principal Office	Interior Door Caulking	17 lf	G	G	5
Nurse Office	12" Beige Floor Tile and Mastic (Black)	400 ft ²	G	G	5
	Interior Door Caulking	51 lf	C	G	5
Main Office to Library Hall	12" Beige Floor Tile and Mastic (Black)	800 ft ²	G	G	5
	Interior Door Caulking	34 lf	G	G	5
	Building Caulking	20 lf	G	G	5
	Piping Fitting Insulation	24 Units	NA	G	5
Pre-K	12" Beige Floor Tile and Mastic (Black)	2640 ft ²	C	MD(1ft ²)	5
	Black Sink Mastic	8 Units	G	G	5
	Piping Fitting Insulation	52 Units	NA	G	5
	Interior Door Caulking	68 lf	G	G	5
Gym	Wood Flooring Materials	8640 ft ²	C	C	5
	Piping Fitting Insulation	23 Units	NA	G	5
	Interior Door Caulking	153 lf	G	G	5
	Building Caulking	140 lf	G	G	5
Boys Locker Room	Interior Door Caulking	51 lf	G	G	5
Girls Locker Room	Interior Door Caulking	51 lf	G	G	5
Kitchen	Interior Door Caulking	102 lf	G	G	5
Cafeteria	Black Residual Mastic (Under 12" Gray Spec Floor Tile)	2760 ft ²	C	C	5
	Interior Door Caulking	102 lf	G	G	5

Appendix A
AHERA Inspection June 2023
Locations of the Identified Asbestos-Containing Materials
Nantucket Elementary School-30 Surfside Rd.

Location	ACM Description	Estimated Quantity	VERTEX 2020 Cond.	VERTEX 2023 Cond.	HA #
Teachers Breakroom (120)	12" Beige Floor Tile and Mastic (Black)	48 ft ²	G	G	5
Building Supervisor (119)	Black Residual Mastic (Under 12" Gray Spec Floor Tile)	160 ft ²	C	C	5
118 and Storage	Black Sink Mastic	1 Unit	G	G	5
D-8	Black Sink Mastic	1 Unit	G	G	5
Mechanical Penthouse	Yellow Duct Mastic	56 lf	G	G	5
Cranberry Corridor	12" Beige Floor Tile and Mastic (Black)	60 ft ²	G	G	5
	Black Residual Mastic (Under 12" Gray Spec Floor Tile)	636 ft ²	C	C	5
	Interior Door Caulking	102 lf	G	G	5
D-1	Black Residual Mastic (Under 12" Gray Spec and 12" Off-White Gray Spec FT)	1500 ft ²	C	C	5
	Black Residual Mastic (Under Carpet and 12" Gray Spec Floor Tile)	400 ft ²	C	C	5
	Interior Door Caulking	34 lf	G	G	5
D-2	Black Residual Mastic (Under 12" Gray Spec and 12" Off-White Gray Spec FT)	1500 ft ²	C	C	5
	Black Residual Mastic (Under Carpet and 12" Gray Spec Floor Tile)	400 ft ²	C	C	5
	Interior Door Caulking	34 lf	G	G	5
D-3	Black Residual Mastic (Under 12" Gray Spec Floor Tile)	1500 ft ²	C	C	5
	Black Residual Mastic (Under Carpet)	400 ft ²	C	C	5
	Black Sink Mastic	1 Unit	G	G	5
	Interior Door Caulking	34 lf	G	G	5
D-4	Black Residual Mastic (Under 12" Gray Spec Floor Tile)	1500 ft ²	C	C	5
	Black Residual Mastic (Under Carpet)	400 ft ²	C	C	5
	Black Sink Mastic	1 Unit	G	G	5
	Interior Door Caulking	34 lf	G	G	5
D-Cluster Area and Hall	Black Residual Mastic (Under 12" Gray Spec Floor Tile)	2000 ft ²	C	C	5
	Black Sink Mastic	2 Units	G	G	5
	Building Caulking	20 lf	G	G	5
Electrical Closet 4	Black Residual Mastic (Under 12" Gray Spec Floor Tile)	48 ft ²	C	C	5
Academic Closet-D	Black Floor Tile Mastic (Under 12" Gray Floor Tile)	360 ft ²	D (16 ft ²)	D (28ft ²)	5

Appendix A AHERA Inspection June 2023 Locations of the Identified Asbestos-Containing Materials Nantucket Elementary School-30 Surfside Rd.					
Location	ACM Description	Estimated Quantity	VERTEX 2020 Cond.	VERTEX 2023 Cond.	HA #
D-Well Area/Hall	Black Residual Mastic (Under Carpet)	660 ft ²	C	C	5
	Black Residual Mastic (Under 12" Gray Spec Floor Tile)	1200 ft ²	C	C	5
	Building Caulking	20 lf	G	G	5
D-6	Black Residual Mastic (Under Carpet)	660 ft ²	C	C	5
	Black Residual Mastic (Under 12" Gray Spec Floor Tile)	720 ft ²	C	C	5
	Black Sink Mastic	2 Units	C	C	5
	Interior Door Caulking	34 lf	G	G	5
D-7	Black Residual Mastic (Under Carpet)	660 ft ²	C	C	5
	Black Residual Mastic (Under 12" Gray Spec Floor Tile)	720 ft ²	C	C	5
	Black Sink Mastic	2 Units	G	G	5
	Interior Door Caulking	34 lf	G	G	5
D to E Hall	Black Residual Mastic (Under 12" Gray Spec Floor Tile)	420 ft ²	C	C	5
	Building Caulking	20 lf	G	G	5
D-9	Black Sink Mastic	3 Units	G	G	5
	Interior Door Caulking	34 lf	G	G	5
E-9 -E-11 Hall	Black Residual Mastic (Under 12" Gray Spec Floor Tile)	168 ft ²	C	C	5
	Building Caulking	20 lf	G	G	5
E-10/E-11	Black Sink Mastic	2 Units	C	C	5
Electrical Room 5	Black Residual Mastic (Under 12" Gray Spec Floor Tile)	60 ft ²	C	C	5
E-1	Black Residual Mastic (Under 12" Gray Spec Floor Tile)	1200 ft ²	C	C	5
	Lab Counter Tops	140 ft ²	G	G	5
	Interior Door Caulking	34 lf	G	G	5
E-2	Black Residual Mastic (Under Painted Floor)	1000 ft ²	C	C	5
	Black Sink Mastic	1 Unit	G	G	5
	Interior Door Caulking	34 lf	G	G	5

Appendix A
AHERA Inspection June 2023
Locations of the Identified Asbestos-Containing Materials
Nantucket Elementary School-30 Surfside Rd.

Location	ACM Description	Estimated Quantity	VERTEX 2020 Cond.	VERTEX 2023 Cond.	HA #
E-3	Black Residual Mastic (Under 12" Beige Spec Floor Tile)	900 ft ²	C	C	5
	Black Sink Mastic	1 Unit	G	G	5
	Interior Door Caulking	34 lf	G	G	5
E-4	Black Residual Mastic (Under 12" Off-White Gray Spec Floor Tile)	900 ft ²	C	C	5
	Black Sink Mastic	1 Unit	G	G	5
	Interior Door Caulking	34 lf	G	G	5
E-5	Black Residual Mastic (Under 12" Off-White Gray Spec Floor Tile)	900 ft ²	C	C	5
	Black Sink Mastic	1 Unit	G	G	5
	Interior Door Caulking	34 lf	G	G	5
E-6	Black Residual Mastic (Under 12" Gray Spec Floor Tile)	300 ft ²	C	MD (3 ft ²)	5
	Black Residual Mastic (Under Carpet)	500 ft ²	C	C	5
	Black Sink Mastic	1 Unit	G	G	5
	Interior Door Caulking	34 lf	G	G	5
E-Cluster Area/Closets and Hall	Black Residual Mastic (Under 12" Gray Spec Floor Tile)	2560 ft ²	C	C	5
	Black Sink Mastic	2 Units	G	G	5
	Building Caulking	60 lf	G	G	5
	Interior Door Caulking	119 lf	G	G	5
E-7	Black Residual Mastic (Under 12" Off-White Gray Spec Floor Tile)	900 ft ²	C	MD (1 ft ²)	5
	Black Sink Mastic	1 Unit	G	G	5
	Interior Door Caulking	34 lf	G	G	5
E-8	Black Residual Mastic (Under 12" Off-White Gray Spec Floor Tile)	600 ft ²	C	C	5
	Black Residual Mastic (Under Carpet)	300 ft ²	C	C	5
	Black Sink Mastic	1 Unit	G	G	5
	Interior Door Caulking	34 lf	G	G	5
E-14 Hall	Black Residual Mastic (Under 12" Gray Spec Floor Tile)	56 ft ²	C	C	5
E-15 Tech and Dark Room	Black Residual Mastic (Under 12" Gray Spec Floor Tile)	440 ft ²	C	C	5

Appendix A
AHERA Inspection June 2023
Locations of the Identified Asbestos-Containing Materials
Nantucket Elementary School-30 Surfside Rd.

Location	ACM Description	Estimated Quantity	VERTEX 2020 Cond.	VERTEX 2023 Cond.	HA #
Bayberry Corridor	Black Residual Mastic (Under 12" Gray Spec Floor Tile)	900 ft ²	C	MD (18 ft ²)	5
	Building Caulking	60 lf	G	G	5
	Interior Door Caulking	51 lf	G	G	5
A-Cluster Area	12" Beige Floor Tile and Mastic (Black)	1440 ft ²	G	G	5
	Black Sink Mastic	2 Units	G	G	5
	Interior Door Caulking	119 lf	G	G	5
	Building Caulking	100 lf	G	G	5
	Piping Fitting Insulation	23 Units	NA	G	5
Early Childhood A-7	Black Residual Mastic (Under Carpet and 12" Gray Spec Floor Tile)	1240 ft ²	C	C	5
	Black Sink Mastic	2 Units	G	G	5
	Building Caulking	20 lf	G	G	5
	Interior Door Caulking	34 lf	G	G	5
	Piping Fitting Insulation	11 Units	NA	G	5
A-6 Nantucket Community	Black Sink Mastic	1 Unit	G	G	5
	Building Caulking	20 lf	G	G	5
	Interior Door Caulking	34 lf	G	G	5
	Piping Fitting Insulation	15 Units	NA	G	5
A-5	Black Sink Mastic	2 Units	G	G	5
	Building Caulking	20 lf	G	G	5
	Interior Door Caulking	34 lf	G	G	5
	Piping Fitting Insulation	12 Units	NA	G	5
A-4	Black Sink Mastic	2 Units	G	G	5
	Interior Door Caulking	51 lf	G	G	5
	Building Caulking	60 lf	G	G	5
	Piping Fitting Insulation	16 Units	NA	G	5

Appendix A
AHERA Inspection June 2023
Locations of the Identified Asbestos-Containing Materials
Nantucket Elementary School-30 Surfside Rd.

Location	ACM Description	Estimated Quantity	VERTEX 2020 Cond.	VERTEX 2023 Cond.	HA #
A-3	Black Sink Mastic	2 Units	G	G	5
	Interior Door Caulking	51 lf	G	G	5
	Building Caulking	60 lf	G	G	5
	Piping Fitting Insulation	13 Units	NA	G	5
A-2	Black Sink Mastic	1 Unit	G	G	5
	Interior Door Caulking	51 lf	G	G	5
	Building Caulking	60 lf	G	G	5
	Piping Fitting Insulation	4 Units	NA	G	5
A-1	Black Sink Mastic	1 Unit	G	G	5
	Interior Door Caulking	51 lf	G	G	5
	Building Caulking	60 lf	G	G	5
	Piping Fitting Insulation	18 Units	NA	G	5
B-Cluster Area	12" Beige Floor Tile and Mastic (Black)	1440 ft ²	G	G	5
	Black Sink Mastic	2 Units	G	G	5
	Building Caulking	100 lf	G	G	5
	Interior Door Caulking	119 lf	G	G	5
	Piping Fitting Insulation	8 Units	NA	G	5
B-6	Black Sink Mastic	1 Unit	G	G	5
	Interior Door Caulking	51 lf	G	G	5
	Building Caulking	30 lf	G	G	5
	Piping Fitting Insulation	21 Units	NA	G	5
B-5	Black Sink Mastic	1 Unit	G	G	5
	Interior Door Caulking	68 lf	G	G	5
	Building Caulking	30 lf	G	G	5
	Piping Fitting Insulation	15 Units	NA	G	5

Appendix A
AHERA Inspection June 2023
Locations of the Identified Asbestos-Containing Materials
Nantucket Elementary School-30 Surfside Rd.

Location	ACM Description	Estimated Quantity	VERTEX 2020 Cond.	VERTEX 2023 Cond.	HA #
B-4	Black Sink Mastic	1 Unit	G	G	5
	Interior Door Caulking	51 lf	G	G	5
	Building Caulking	40 lf	G	G	5
	Piping Fitting Insulation	4 Units	NA	G	5
B-3	Black Sink Mastic	1 Unit	G	G	5
	Interior Door Caulking	51 lf	G	G	5
	Building Caulking	40 lf	G	G	5
	Piping Fitting Insulation	18 Units	NA	G	5
B-2	Black Sink Mastic	1 Unit	G	G	5
	Interior Door Caulking	34 lf	G	G	5
	Building Caulking	40 lf	G	G	5
	Piping Fitting Insulation	15 Units	NA	G	5
B-1	Black Sink Mastic	1 Unit	G	G	5
	Interior Door Caulking	34 lf	G	G	5
	Building Caulking	60 lf	G	G	5
	Piping Fitting Insulation	9 Units	NA	G	5
Reading Room	12" Beige Floor Tile and Mastic (Black)	1250 ft ²	G	G	5
	Black Residual Mastic (Under 12" Gray Spec Floor Tile)	250 ft ²	C	C	5
	Interior Door Caulking	51 lf	G	G	5
	Piping Fitting Insulation	8 Units	NA	G	5
C-Cluster Area	12" Beige Floor Tile and Mastic (Black)	1860 ft ²	G	G	5
	Black Sink Mastic	1 Unit	G	G	5
	Building Caulking	100 lf	G	G	5
	Interior Door Caulking	119 lf	G	G	5
	Piping Fitting Insulation	7 Units	NA	G	5
C-7 Storage	12" Beige Floor Tile and Mastic (Black)	100 ft ²	G	C	5

Appendix A
AHERA Inspection June 2023
Locations of the Identified Asbestos-Containing Materials
Nantucket Elementary School-30 Surfside Rd.

Location	ACM Description	Estimated Quantity	VERTEX 2020 Cond.	VERTEX 2023 Cond.	HA #
C-6	Black Sink Mastic	1 Unit	G	G	5
	Interior Door Caulking	51 lf	G	G	5
	Building Caulking	30 lf	G	G	5
	Piping Fitting Insulation	15 Units	NA	G	5
C-5	Black Sink Mastic	1 Unit	G	G	5
	Interior Door Caulking	51 lf	G	G	5
	Building Caulking	40 lf	G	G	5
	Piping Fitting Insulation	7 Units	NA	G	5
C-4	Black Sink Mastic	1 Unit	G	G	5
	Interior Door Caulking	51 lf	G	G	5
	Building Caulking	40 lf	G	G	5
	Piping Fitting Insulation	18 Units	NA	G	5
C-3	Black Sink Mastic	1 Unit	G	G	5
	Interior Door Caulking	51 lf	G	G	5
	Building Caulking	40 lf	G	G	5
	Piping Fitting Insulation	4 Units	NA	G	5
C-2	Black Sink Mastic	1 Unit	G	G	5
	Interior Door Caulking	51 lf	G	G	5
	Building Caulking	40 lf	G	G	5
	Piping Fitting Insulation	11 Units	NA	G	5
C-1	Black Sink Mastic	1 Unit	G	G	5
	Interior Door Caulking	51 lf	G	G	5
	Building Caulking	20 lf	G	G	5
	Piping Fitting Insulation	11 Units	NA	G	5

Appendix A
AHERA Inspection June 2023
Locations of the Identified Asbestos-Containing Materials
Nantucket Elementary School-30 Surfside Rd.

Location	ACM Description	Estimated Quantity	VERTEX 2020 Cond.	VERTEX 2023 Cond.	HA #
Library Area	Black Sink Mastic	2 Units	G	G	5
	Interior Door Caulking	68 lf	G	G	5
	Building Caulking	30 lf	G	G	5
	Piping Fitting Insulation	6 Units	NA	G	5
Library Hall Area	Interior Door Caulking	289 lf	G	G	5
	Building Caulking	120 lf	G	G	5
	Piping Fitting Insulation	53 Units	NA	G	5
110	Black Sink Mastic	1 Unit	G	G	5
	Interior Door Caulking	34 lf	G	G	5
	Building Caulking	20 lf	G	G	5

Notes:

ft ² = Square Foot	Cond. = Condition	U = Unknown	NA = Not Accessible
lf = Linear Foot	G = Good	C = Covered	
Unit = Each	MD = Minor Damage	M = Miscellaneous	
Y= Yes	D = Damaged	S= Surfacing	
N = No	Fri. = Friable	TSI = Thermal System Insulation	

HA # = Homogenous Area Hazard Assessment Category

- 1 = Damaged/Significantly Damaged Thermal System Insulation
- 2 = Damaged Friable Surfacing ACBM
- 3 = Significantly Damaged Friable Surfacing ACBM
- 4 = Damaged or Significantly Damaged Friable Miscellaneous ACBM
- 5 = ACBM with Potential for Damage



Nantucket Elementary School
30 Surfside Road Nantucket, MA
Project # 89066

6 = ACBM with Potential for Significant Damage

7 = Any Remaining Friable ACBM or Friable Suspected ACBM

NA = Not Applicable

APPENDIX B

ESTIMATED RESOURCES REQUIRED TO COMPLETE THE RESPONSE ACTIONS

Appendix B
AHERA Inspection July 2020
Estimated Resources to Complete Response Actions
Nantucket Elementary School-30 Surfside Rd.

Location	ACM Description	Estimated Quantity	Recommended Response Action	Estimated Cost	Recommended Date of Completed Response Action	Date of Completed Response Action
Academic Closet-D	Black Floor Tile Mastic	28 ft ²	Remove/Replace Damaged Floor Tile	\$800.00	January 2024	
E-6	Black Floor Tile Mastic	3 ft ²	Remove/Replace Damaged Floor Tile	\$250.00	January 2024	
E-7	Black Floor Tile Mastic	1 ft ²	Remove/Replace Damaged Floor Tile	\$100.00	January 2024	
Bayberry Corridor	Black Floor Tile Mastic	18 ft ²	Remove/Replace Damaged Floor Tile	\$800.00	January 2024	
Pre-K	Black Floor Tile Mastic	1 ft ²	Remove/Replace Damaged Floor Tile	\$100.00	January 2024	

Notes:

ft² = Square Foot

* The estimated cost provided above is developed from current Abatement Contractor Unit pricing. These estimates will vary according to competitive bidding, accessibility, location, and condition of ACMs, phasing of work, etc. In addition, the costs above do not include mobilization of the Abatement Contractor, Abatement Work Plan/Design, Project Monitoring and/or Clearance Testing Services for the completion of the response actions. Please refer for below unit pricing regarding costs for the Contractor Mobilization and Clearance Testing Services:

- Abatement Work Plan/Design Specification = \$500-\$2,500.00
- Abatement Contactor Mobilization = \$1,500.00-\$2,500.00
- Project Monitoring/Clearance Testing = \$520.00-\$600.00/per shift
- Transmission Electron Microcopy (TEM) Analysis = \$75.00-\$100.00/sample
- Phase Contrast Microscopy (PCM) Analysis = No Charge -\$15.00/sample
- Clearance Report Preparation = \$350.00-\$800.00

*The estimated cost provided above does not include costs that may be associated with two-hour asbestos awareness training, OSHA 16-hr Operations and Maintenance Training, and/or the labor to conduct the required six-month surveillance re-inspections. Please refer below for estimated costs that may be associated with the mentioned above:

2-Hour Asbestos Awareness Training = \$75/person



Nantucket Elementary School
30 Surfside Road Nantucket, MA
Project # 88066

OSHA 16-hr Operations and Maintenance Training = \$300/person

Six-Month Periodic Surveillance Inspection = \$400/inspection

Estimated Resources

Page 2

APPENDIX C

ESTIMATED RESOURCES REQUIRED FOR THE ABATEMENT OF THE IDENTIFIED ACBMs

Appendix C			
AHERA Inspection June 2023			
Estimated Costs For the Removal of the Identified Asbestos-Containing Materials			
Nantucket Elementary School-30 Surfside Rd.			
Location	ACM Description	Estimated Quantity	Estimated Cost
Lobby	Black Residual Mastic (Under Carpet and 12" Gray Spec Floor Tile)	1000 ft ²	\$11,000.00
	Interior Door Caulking	102 lf	\$1,020.00
Music Room (101)	12" Red Floor Tile and Mastic (Black)	400 ft ²	\$4,400.00
	Black Residual Mastic (Under 12" Gray Spec and 12" Off-White Gray Spec FT)	50 ft ²	\$550.00
	Piping Fitting Insulation	4 Units	\$100.00
	Interior Door Caulking	34 lf	\$340.00
Main Office	Interior Door Caulking	17 lf	\$170.00
Principal Office	Interior Door Caulking	17 lf	\$170.00
Nurse Office	12" Beige Floor Tile and Mastic (Black)	400 ft ²	\$4,400.00
	Interior Door Caulking	51 lf	\$510.00
Main Office to Library Hall	12" Beige Floor Tile and Mastic (Black)	800 ft ²	\$8,800.00
	Interior Door Caulking	34 lf	\$340.00
	Building Caulking	20 lf	\$200.00
	Piping Fitting Insulation	24 Units	\$600.00
Pre-K	12" Beige Floor Tile and Mastic (Black)	2640 ft ²	\$29,040.00
	Black Sink Mastic	8 Units	\$400.00
	Piping Fitting Insulation	52 Units	\$1,300.00
	Interior Door Caulking	68 lf	\$680.00
Gym	Wood Flooring Materials	8640 ft ²	\$51,840.00
	Piping Fitting Insulation	23 Units	\$575.00
	Interior Door Caulking	153 lf	\$1,530.00
	Building Caulking	140 lf	\$1,400.00
Boys Locker Room	Interior Door Caulking	51 lf	\$510.00
Girls Locker Room	Interior Door Caulking	51 lf	\$510.00
Kitchen	Interior Door Caulking	102 lf	\$1,020.00
Cafeteria	Black Residual Mastic (Under 12" Gray Spec Floor Tile)	2760 ft ²	\$30,360.00
	Interior Door Caulking	102 lf	\$1,020.00

Appendix C			
AHERA Inspection June 2023			
Estimated Costs For the Removal of the Identified Asbestos-Containing Materials			
Nantucket Elementary School-30 Surfside Rd.			
Location	ACM Description	Estimated Quantity	Estimated Cost
Teachers Breakroom (120)	12" Beige Floor Tile and Mastic (Black)	48 ft ²	\$528.00
Building Supervisor (119)	Black Residual Mastic (Under 12" Gray Spec Floor Tile)	160 ft ²	\$1,760.00
118 and Storage	Black Sink Mastic	1 Unit	\$50.00
D-8	Black Sink Mastic	1 Unit	\$50.00
Mechanical Penthouse	Yellow Duct Mastic	56 lf	\$560.00
Cranberry Corridor	12" Beige Floor Tile and Mastic (Black)	60 ft ²	\$660.00
	Black Residual Mastic (Under 12" Gray Spec Floor Tile)	636 ft ²	\$6,996.00
	Interior Door Caulking	102 lf	\$1,020.00
D-1	Black Residual Mastic (Under 12" Gray Spec and 12" Off-White Gray Spec FT)	1500 ft ²	\$16,500.00
	Black Residual Mastic (Under Carpet and 12" Gray Spec Floor Tile)	400 ft ²	\$4,400.00
	Interior Door Caulking	34 lf	\$340.00
D-2	Black Residual Mastic (Under 12" Gray Spec and 12" Off-White Gray Spec FT)	1500 ft ²	\$16,500.00
	Black Residual Mastic (Under Carpet and 12" Gray Spec Floor Tile)	400 ft ²	\$4,400.00
	Interior Door Caulking	34 lf	\$340.00
D-3	Black Residual Mastic (Under 12" Gray Spec Floor Tile)	1500 ft ²	\$16,500.00
	Black Residual Mastic (Under Carpet)	400 ft ²	\$4,400.00
	Black Sink Mastic	1 Unit	\$50.00
	Interior Door Caulking	34 lf	\$340.00
D-4	Black Residual Mastic (Under 12" Gray Spec Floor Tile)	1500 ft ²	\$16,500.00
	Black Residual Mastic (Under Carpet)	400 ft ²	\$4,400.00
	Black Sink Mastic	1 Unit	\$50.00
	Interior Door Caulking	34 lf	\$340.00
D-Cluster Area and Hall	Black Residual Mastic (Under 12" Gray Spec Floor Tile)	2000 ft ²	\$22,000.00
	Black Sink Mastic	2 Units	\$100.00
	Building Caulking	20 lf	\$200.00
Electrical Closet 4	Black Residual Mastic (Under 12" Gray Spec Floor Tile)	48 ft ²	\$528.00
Academic Closet-D	Black Floor Tile Mastic (Under 12" Gray Floor Tile)	360 ft ²	\$3,960.00

Appendix C			
AHERA Inspection June 2023			
Estimated Costs For the Removal of the Identified Asbestos-Containing Materials			
Nantucket Elementary School-30 Surfside Rd.			
Location	ACM Description	Estimated Quantity	Estimated Cost.
D-Well Area/Hall	Black Residual Mastic (Under Carpet)	660 ft ²	\$7,260.00
	Black Residual Mastic (Under 12" Gray Spec Floor Tile)	1200 ft ²	\$13,200.00
	Building Caulking	20 lf	\$200.00
D-6	Black Residual Mastic (Under Carpet)	660 ft ²	\$7,260.00
	Black Residual Mastic (Under 12" Gray Spec Floor Tile)	720 ft ²	\$7,920.00
	Black Sink Mastic	2 Units	\$100.00
	Interior Door Caulking	34 lf	\$340.00
D-7	Black Residual Mastic (Under Carpet)	660 ft ²	\$7,260.00
	Black Residual Mastic (Under 12" Gray Spec Floor Tile)	720 ft ²	\$7,920.00
	Black Sink Mastic	2 Units	\$100.00
	Interior Door Caulking	34 lf	\$374.00
D to E Hall	Black Residual Mastic (Under 12" Gray Spec Floor Tile)	420 ft ²	\$4,620.00
	Building Caulking	20 lf	\$200.00
D-9	Black Sink Mastic	3 Units	\$150.00
	Interior Door Caulking	34 lf	\$340.00
E-9 -E-11 Hall	Black Residual Mastic (Under 12" Gray Spec Floor Tile)	168 ft ²	\$1,848.00
	Building Caulking	20 lf	\$200.00
E-10/E-11	Black Sink Mastic	2 Units	\$100.00
Electrical Room 5	Black Residual Mastic (Under 12" Gray Spec Floor Tile)	60 ft ²	\$660.00
E-1	Black Residual Mastic (Under 12" Gray Spec Floor Tile)	1200 ft ²	\$13,200.00
	Lab Counter Tops	140 ft ²	\$840.00
	Interior Door Caulking	34 lf	\$340.00
E-2	Black Residual Mastic (Under Painted Floor)	1000 ft ²	\$11,000.00
	Black Sink Mastic	1 Unit	\$50.00
	Interior Door Caulking	34 lf	\$340.00

Appendix C
AHERA Inspection June 2023
Estimated Costs For the Removal of the Identified Asbestos-Containing Materials
Nantucket Elementary School-30 Surfside Rd.

Location	ACM Description	Estimated Quantity	Estimated Cost
E-3	Black Residual Mastic (Under 12" Beige Spec Floor Tile)	900 ft ²	\$9,900.00
	Black Sink Mastic	1 Unit	\$50.00
	Interior Door Caulking	34 lf	\$340.00
E-4	Black Residual Mastic (Under 12" Off-White Gray Spec Floor Tile)	900 ft ²	\$9,900.00
	Black Sink Mastic	1 Unit	\$50.00
	Interior Door Caulking	34 lf	\$340.00
E-5	Black Residual Mastic (Under 12" Off-White Gray Spec Floor Tile)	900 ft ²	\$9,900.00
	Black Sink Mastic	1 Unit	\$50.00
	Interior Door Caulking	34 lf	\$340.00
E-6	Black Residual Mastic (Under 12" Gray Spec Floor Tile)	300 ft ²	\$3,300.00
	Black Residual Mastic (Under Carpet)	500 ft ²	\$5,500.00
	Black Sink Mastic	1 Unit	\$50.00
	Interior Door Caulking	34 lf	\$340.00
E-Cluster Area/Closets and Hall	Black Residual Mastic (Under 12" Gray Spec Floor Tile)	2560 ft ²	\$28,160.00
	Black Sink Mastic	2 Units	\$100.00
	Building Caulking	60 lf	\$600.00
	Interior Door Caulking	119 lf	\$1,190.00
E-7	Black Residual Mastic (Under 12" Off-White Gray Spec Floor Tile)	900 ft ²	\$9,900.00
	Black Sink Mastic	1 Unit	\$50.00
	Interior Door Caulking	34 lf	\$340.00
E-8	Black Residual Mastic (Under 12" Off-White Gray Spec Floor Tile)	600 ft ²	\$6,600.00
	Black Residual Mastic (Under Carpet)	300 ft ²	\$3,300.00
	Black Sink Mastic	1 Unit	\$50.00
	Interior Door Caulking	34 lf	\$340.00
E-14 Hall	Black Residual Mastic (Under 12" Gray Spec Floor Tile)	56 ft ²	\$616.00
E-15 Tech and Dark Room	Black Residual Mastic (Under 12" Gray Spec Floor Tile)	440 ft ²	\$4,840.00

Appendix C AHERA Inspection June 2023 Estimated Costs For the Removal of the Identified Asbestos-Containing Materials Nantucket Elementary School-30 Surfside Rd.			
Location	ACM Description	Estimated Quantity	Estimated Cost
Bayberry Corridor	Black Residual Mastic (Under 12" Gray Spec Floor Tile)	900 ft ²	\$9,900.00
	Building Caulking	60 lf	\$600.00
	Interior Door Caulking	51 lf	\$510.00
A-Cluster Area	12" Beige Floor Tile and Mastic (Black)	1440 ft ²	\$15,840.00
	Black Sink Mastic	2 Units	\$100.00
	Interior Door Caulking	119 lf	\$1,190.00
	Building Caulking	100 lf	\$1,000.00
Early Childhood A-7	Piping Fitting Insulation	23 Units	\$575.00
	Black Residual Mastic (Under Carpet and 12" Gray Spec Floor Tile)	1240 ft ²	\$13,640.00
	Black Sink Mastic	2 Units	\$100.00
	Building Caulking	20 lf	\$200.00
	Interior Door Caulking	34 lf	\$340.00
A-6 Nantucket Community	Piping Fitting Insulation	11 Units	\$275.00
	Black Sink Mastic	1 Unit	\$50.00
	Building Caulking	20 lf	\$200.00
	Interior Door Caulking	34 lf	\$340.00
A-5	Piping Fitting Insulation	15 Units	\$375.00
	Black Sink Mastic	2 Units	\$100.00
	Building Caulking	20 lf	\$200.00
	Interior Door Caulking	34 lf	\$340.00
A-4	Piping Fitting Insulation	12 Units	\$300.00
	Black Sink Mastic	2 Units	\$100.00
	Interior Door Caulking	51 lf	\$510.00
	Building Caulking	60 lf	\$600.00
	Piping Fitting Insulation	16 Units	\$400.00

Appendix C			
AHERA Inspection June 2023			
Estimated Costs For the Removal of the Identified Asbestos-Containing Materials			
Nantucket Elementary School-30 Surfside Rd.			
Location	ACM Description	Estimated Quantity	Estimated Cost
A-3	Black Sink Mastic	2 Units	\$100.00
	Interior Door Caulking	51 lf	\$510.00
	Building Caulking	60 lf	\$600.00
	Piping Fitting Insulation	13 Units	\$325.00
A-2	Black Sink Mastic	1 Unit	\$50.00
	Interior Door Caulking	51 lf	\$510.00
	Building Caulking	60 lf	\$600.00
	Piping Fitting Insulation	4 Units	\$100.00
A-1	Black Sink Mastic	1 Unit	\$50.00
	Interior Door Caulking	51 lf	\$510.00
	Building Caulking	60 lf	\$600.00
	Piping Fitting Insulation	18 Units	\$450.00
B-Cluster Area	12" Beige Floor Tile and Mastic (Black)	1440 ft ²	\$15,840.00
	Black Sink Mastic	2 Units	\$100.00
	Building Caulking	100 lf	\$1,000.00
	Interior Door Caulking	119 lf	\$1,190.00
	Piping Fitting Insulation	8 Units	\$200.00
B-6	Black Sink Mastic	1 Unit	\$50.00
	Interior Door Caulking	51 lf	\$510.00
	Building Caulking	30 lf	\$300.00
	Piping Fitting Insulation	21 Units	\$525.00
B-5	Black Sink Mastic	1 Unit	\$50.00
	Interior Door Caulking	68 lf	\$680.00
	Building Caulking	30 lf	\$300.00
	Piping Fitting Insulation	15 Units	\$375.00

Appendix C AHERA Inspection June 2023 Estimated Costs For the Removal of the Identified Asbestos-Containing Materials Nantucket Elementary School-30 Surfside Rd.			
Location	ACM Description	Estimated Quantity	Estimated Cost
B-4	Black Sink Mastic	1 Unit	\$50.00
	Interior Door Caulking	51 lf	\$510.00
	Building Caulking	40 lf	\$400.00
	Piping Fitting Insulation	4 Units	\$100.00
B-3	Black Sink Mastic	1 Unit	\$50.00
	Interior Door Caulking	51 lf	\$510.00
	Building Caulking	40 lf	\$400.00
	Piping Fitting Insulation	18 Units	\$450.00
B-2	Black Sink Mastic	1 Unit	\$50.00
	Interior Door Caulking	34 lf	\$340.00
	Building Caulking	40 lf	\$400.00
	Piping Fitting Insulation	15 Units	\$375.00
B-1	Black Sink Mastic	1 Unit	\$50.00
	Interior Door Caulking	34 lf	\$340.00
	Building Caulking	60 lf	\$600.00
	Piping Fitting Insulation	9 Units	\$225.00
Reading Room	12" Beige Floor Tile and Mastic (Black)	1250 ft ²	\$13,750.00
	Black Residual Mastic (Under 12" Gray Spec Floor Tile)	250 ft ²	\$2,750.00
	Interior Door Caulking	51 lf	\$510.00
	Piping Fitting Insulation	8 Units	\$200.00
C-Cluster Area	12" Beige Floor Tile and Mastic (Black)	1860 ft ²	\$20,460.00
	Black Sink Mastic	1 Unit	\$50.00
	Building Caulking	100 lf	\$1,000.00
	Interior Door Caulking	119 lf	\$1,190.00
	Piping Fitting Insulation	7 Units	\$175.00
C-7 Storage	12" Beige Floor Tile and Mastic (Black)	100 ft ²	\$1,100.00

Appendix C AHERA Inspection June 2023 Estimated Costs For the Removal of the Identified Asbestos-Containing Materials Nantucket Elementary School-30 Surfside Rd.			
Location	ACM Description	Estimated Quantity	Estimated Cost
C-6	Black Sink Mastic	1 Unit	\$50.00
	Interior Door Caulking	51 lf	\$510.00
	Building Caulking	30 lf	\$300.00
	Piping Fitting Insulation	15 Units	\$375.00
C-5	Black Sink Mastic	1 Unit	\$50.00
	Interior Door Caulking	51 lf	\$510.00
	Building Caulking	40 lf	\$400.00
	Piping Fitting Insulation	7 Units	\$175.00
C-4	Black Sink Mastic	1 Unit	\$50.00
	Interior Door Caulking	51 lf	\$510.00
	Building Caulking	40 lf	\$400.00
	Piping Fitting Insulation	18 Units	\$450.00
C-3	Black Sink Mastic	1 Unit	\$50.00
	Interior Door Caulking	51 lf	\$510.00
	Building Caulking	40 lf	\$400.00
	Piping Fitting Insulation	4 Units	\$100.00
C-2	Black Sink Mastic	1 Unit	\$50.00
	Interior Door Caulking	51 lf	\$510.00
	Building Caulking	40 lf	\$400.00
	Piping Fitting Insulation	11 Units	\$275.00
C-1	Black Sink Mastic	1 Unit	\$50.00
	Interior Door Caulking	51 lf	\$510.00
	Building Caulking	20 lf	\$200.00
	Piping Fitting Insulation	11 Units	\$275.00

Appendix C AHERA Inspection June 2023 Estimated Costs For the Removal of the Identified Asbestos-Containing Materials Nantucket Elementary School-30 Surfside Rd.			
Location	ACM Description	Estimated Quantity	Estimated Cost
Library Area	Black Sink Mastic	2 Units	\$100.00
	Interior Door Caulking	68 lf	\$680.00
	Building Caulking	30 lf	\$300.00
	Piping Fitting Insulation	6 Units	\$150.00
Library Hall Area	Interior Door Caulking	289 lf	\$2,890.00
	Building Caulking	120 lf	\$1,200.00
	Piping Fitting Insulation	53 Units	\$1,325.00
110	Black Sink Mastic	1 Unit	\$50.00
	Interior Door Caulking	34 lf	\$340.00
	Building Caulking	20 lf	\$200.00

Notes:

ft² = Square Foot

lf = Linear Foot

Unit = Each

APPENDIX D
PERSONNEL CERTIFICATIONS

**The Vertex Companies, LLC
ACCREDITATION PAGE**

Accredited Inspector

Name: Jason Mohre

Accreditation Number: AI000262



Signature: _____

Date: 7/20/23

Accredited Management Planner

Name: Jason Mohre

Accreditation Number: AP000080



Signature: _____

Date: 7/20/23

APPENDIX E

DESIGNATED PERSON ASSURANCES SIGN-OFF

DESIGNATED PERSON ASSURANCES

In accordance with 40 CFR ' 763.93(i) of the Environmental Protection Agency Asbestos-Containing Material in Schools regulation, the undersigned Local Education Agency (LEA) Designated Person (DP) hereby certifies that the following general responsibilities of the LEA under 40 CFR ' 763.84 have been or will be met:

1. Ensure that the activities of any persons who perform inspections, reinspections, and periodic surveillance, develop and update management plans, and develop and implement response actions, including operations and maintenance, are carried out in accordance with Part 763, Subpart E.
2. Ensure that all custodial and maintenance employees are properly trained as required by Part 763, Subpart E and other applicable Federal and/or State regulations (e.g., the Occupational Safety and Health Administration asbestos standard for construction, the EPA worker protection rule, or applicable State regulations).
3. Ensure that workers and building occupants, or their legal guardians, are informed at least once each school year about inspections, response actions, and post-response action activities, including periodic reinspection and surveillance activities that are planned or in progress.
4. Ensure that short-term workers (e.g., telephone repair workers, utility workers, or exterminators) who may come in contact with asbestos in a school are provided information regarding the locations for Asbestos-Containing Building Materials (ACBM) and suspected ACBM assumed to be Asbestos-Containing Materials (ACM).
5. Ensure that warning labels are posted in accordance with ' 40 CFR 763.95.
6. Ensure that management plans are available for inspection and notification of such availability has been provided as specified in the management plan under ' 40 CFR 763.93(g).
7. Designate a person to ensure that requirements under ' 763.84 are properly implemented and ensure that the designated person receives adequate training to perform duties assigned under ' 763.84. Such training shall provide, as necessary, basic knowledge of: health effects of asbestos; detection, identification, and assessment of ACM; options for controlling ACBM; asbestos management programs; relevant Federal and State regulations concerning asbestos, including those in Part 763, Subpart E and those of the Occupational Safety and Health Administration, U.S. Department of Transportation and the U.S. Environmental Protection Agency.
8. Consider whether any conflict of interest may arise from the inter-relationship among accredited personnel and whether that should influence the selection of accredited personnel to perform activities under Part 763, Subpart E.

Name of Designated Person:

Designated Person's Signature:

Date:

APPENDIX F
SIX-MONTH SURVEILLANCE

AHERA Six-Month Surveillance Inspection Date: _____ **(Print Name):** _____

Signature: _____

Nantucket Elementary School-30 Surfside Rd.

Location	ACM Description	Estimated Quantity	VERTEX 2023 Cond.	Jan. 2024 Cond.	July 2024 Cond.	Jan. 2025 Cond.	July 2025 Cond.
Lobby	Black Residual Mastic (Under Carpet and 12" Gray Spec Floor Tile)	1000 ft ²	C				
	Interior Door Caulking	102 lf	G				
Music Room (101)	12" Red Floor Tile and Mastic (Black)	400 ft ²	G				
	Black Residual Mastic (Under 12" Gray Spec and 12" Off-White Gray Spec FT)	50 ft ²	G				
	Piping Fitting Insulation	4 Units	G				
	Interior Door Caulking	34 lf	G				
Main Office	Interior Door Caulking	17 lf	G				
Principal Office	Interior Door Caulking	17 lf	G				
Nurse Office	12" Beige Floor Tile and Mastic (Black)	400 ft ²	G				
	Interior Door Caulking	51 lf	G				
Main Office to Library Hall	12" Beige Floor Tile and Mastic (Black)	800 ft ²	G				
	Interior Door Caulking	34 lf	G				
	Building Caulking	20 lf	G				
	Piping Fitting Insulation	24 Units	G				
Pre-K	12" Beige Floor Tile and Mastic (Black)	2640 ft ²	MD(1ft ²)				
	Black Sink Mastic	8 Units	G				
	Piping Fitting Insulation	52 Units	G				
	Interior Door Caulking	68 lf	G				
Gym	Wood Flooring Materials	8640 ft ²	C				
	Piping Fitting Insulation	23 Units	G				
	Interior Door Caulking	153 lf	G				
	Building Caulking	140 lf	G				
Boys Locker Room	Interior Door Caulking	51 lf	G				
Girls Locker Room	Interior Door Caulking	51 lf	G				
Kitchen	Interior Door Caulking	102 lf	G				
Cafeteria	Black Residual Mastic (Under 12" Gray Spec Floor Tile)	2760 ft ²	C				
	Interior Door Caulking	102 lf	G				

AHERA Six-Month Surveillance Inspection Date: _____ (Print Name): _____

Signature: _____

Nantucket Elementary School-30 Surfside Rd.

Location	ACM Description	Estimated Quantity	VERTEX 2023 Cond.	Jan. 2024 Cond.	July 2024 Cond.	Jan. 2025 Cond.	July 2025 Cond.
Teachers Breakroom (120)	12" Beige Floor Tile and Mastic (Black)	48 ft ²	G				
Building Supervisor (119)	Black Residual Mastic (Under 12" Gray Spec Floor Tile)	160 ft ²	C				
118 and Storage	Black Sink Mastic	1 Unit	G				
D-8	Black Sink Mastic	1 Unit	G				
Mechanical Penthouse	Yellow Duct Mastic	56 lf	G				
Cranberry Corridor	12" Beige Floor Tile and Mastic (Black)	60 ft ²	G				
	Black Residual Mastic (Under 12" Gray Spec Floor Tile)	636 ft ²	C				
	Interior Door Caulking	102 lf	G				
D-1	Black Residual Mastic (Under 12" Gray Spec and 12" Off-White Gray Spec FT)	1500 ft ²	C				
	Black Residual Mastic (Under Carpet and 12" Gray Spec Floor Tile)	400 ft ²	C				
	Interior Door Caulking	34 lf	G				
D-2	Black Residual Mastic (Under 12" Gray Spec and 12" Off-White Gray Spec FT)	1500 ft ²	C				
	Black Residual Mastic (Under Carpet and 12" Gray Spec Floor Tile)	400 ft ²	C				
	Interior Door Caulking	34 lf	G				
D-3	Black Residual Mastic (Under 12" Gray Spec Floor Tile)	1500 ft ²	C				
	Black Residual Mastic (Under Carpet)	400 ft ²	C				
	Black Sink Mastic	1 Unit	G				
	Interior Door Caulking	34 lf	G				
D-4	Black Residual Mastic (Under 12" Gray Spec Floor Tile)	1500 ft ²	C				
	Black Residual Mastic (Under Carpet)	400 ft ²	C				
	Black Sink Mastic	1 Unit	G				
	Interior Door Caulking	34 lf	G				
D-Cluster Area and Hall	Black Residual Mastic (Under 12" Gray Spec Floor Tile)	2000 ft ²	C				
	Black Sink Mastic	2 Units	G				
	Building Caulking	20 lf	G				
Electrical Closet 4	Black Residual Mastic (Under 12" Gray Spec Floor Tile)	48 ft ²	C				
Academic Closet-D	Black Floor Tile Mastic (Under 12" Gray Floor Tile)	360 ft ²	D (28ft ²)				

AHERA Six-Month Surveillance Inspection Date: _____ **(Print Name):** _____

Signature: _____

Nantucket Elementary School-30 Surfside Rd.

Location	ACM Description	Estimated Quantity	VERTEX 2023 Cond.	Jan. 2024 Cond.	July 2024 Cond.	Jan. 2025 Cond.	July 2025 Cond.
D-Well Area/Hall	Black Residual Mastic (Under Carpet)	660 ft ²	C				
	Black Residual Mastic (Under 12" Gray Spec Floor Tile)	1200 ft ²	C				
	Building Caulking	20 lf	G				
D-6	Black Residual Mastic (Under Carpet)	660 ft ²	C				
	Black Residual Mastic (Under 12" Gray Spec Floor Tile)	720 ft ²	C				
	Black Sink Mastic	2 Units	C				
	Interior Door Caulking	34 lf	G				
D-7	Black Residual Mastic (Under Carpet)	660 ft ²	C				
	Black Residual Mastic (Under 12" Gray Spec Floor Tile)	720 ft ²	C				
	Black Sink Mastic	2 Units	G				
	Interior Door Caulking	34 lf	G				
D to E Hall	Black Residual Mastic (Under 12" Gray Spec Floor Tile)	420 ft ²	C				
	Building Caulking	20 lf	G				
	Interior Door Caulking	34 lf	G				
D-9	Black Sink Mastic	3 Units	G				
	Interior Door Caulking	34 lf	G				
E-9 -E-11 Hall	Black Residual Mastic (Under 12" Gray Spec Floor Tile)	168 ft ²	C				
	Building Caulking	20 lf	G				
E-10/E-11	Black Sink Mastic	2 Units	C				
Electrical Room 5	Black Residual Mastic (Under 12" Gray Spec Floor Tile)	60 ft ²	C				
E-1	Black Residual Mastic (Under 12" Gray Spec Floor Tile)	1200 ft ²	C				
	Lab Counter Tops	140 ft ²	G				
	Interior Door Caulking	34 lf	G				
E-2	Black Residual Mastic (Under Painted Floor)	1000 ft ²	C				
	Black Sink Mastic	1 Unit	G				
	Interior Door Caulking	34 lf	G				

AHERA Six-Month Surveillance Inspection Date: _____ (Print Name): _____

Signature: _____

Nantucket Elementary School-30 Surfside Rd.

Location	ACM Description	Estimated Quantity	VERTEX 2023 Cond.	Jan. 2024 Cond.	July 2024 Cond.	Jan. 2025 Cond.	July 2025 Cond.
E-3	Black Residual Mastic (Under 12" Beige Spec Floor Tile)	900 ft ²	C				
	Black Sink Mastic	1 Unit	G				
	Interior Door Caulking	34 lf	G				
E-4	Black Residual Mastic (Under 12" Off-White Gray Spec Floor Tile)	900 ft ²	C				
	Black Sink Mastic	1 Unit	G				
	Interior Door Caulking	34 lf	G				
E-5	Black Residual Mastic (Under 12" Off-White Gray Spec Floor Tile)	900 ft ²	C				
	Black Sink Mastic	1 Unit	G				
	Interior Door Caulking	34 lf	G				
E-6	Black Residual Mastic (Under 12" Gray Spec Floor Tile)	300 ft ²	MD (3 ft ²)				
	Black Residual Mastic (Under Carpet)	500 ft ²	C				
	Black Sink Mastic	1 Unit	G				
	Interior Door Caulking	34 lf	G				
E-Cluster Area/Closets and Hall	Black Residual Mastic (Under 12" Gray Spec Floor Tile)	2560 ft ²	C				
	Black Sink Mastic	2 Units	G				
	Building Caulking	60 lf	G				
	Interior Door Caulking	119 lf	G				
E-7	Black Residual Mastic (Under 12" Off-White Gray Spec Floor Tile)	900 ft ²	MD (1 ft ²)				
	Black Sink Mastic	1 Unit	G				
	Interior Door Caulking	34 lf	G				
E-8	Black Residual Mastic (Under 12" Off-White Gray Spec Floor Tile)	600 ft ²	C				
	Black Residual Mastic (Under Carpet)	300 ft ²	C				
	Black Sink Mastic	1 Unit	G				
	Interior Door Caulking	34 lf	G				
E-14 Hall	Black Residual Mastic (Under 12" Gray Spec Floor Tile)	56 ft ²	C				
E-15 Tech and Dark Room	Black Residual Mastic (Under 12" Gray Spec Floor Tile)	440 ft ²	C				

AHERA Six-Month Surveillance Inspection Date: _____ (Print Name): _____

Signature: _____

Nantucket Elementary School-30 Surfside Rd.

Location	ACM Description	Estimated Quantity	VERTEX 2023 Cond.	Jan. 2024 Cond.	July 2024 Cond.	Jan. 2025 Cond.	July 2025 Cond.
Bayberry Corridor	Black Residual Mastic (Under 12" Gray Spec Floor Tile)	900 ft ²	MD (18 ft ²)				
	Building Caulking	60 lf	G				
	Interior Door Caulking	51 lf	G				
A-Cluster Area	12" Beige Floor Tile and Mastic (Black)	1440 ft ²	G				
	Black Sink Mastic	2 Units	G				
	Interior Door Caulking	119 lf	G				
	Building Caulking	100 lf	G				
	Piping Fitting Insulation	23 Units	G				
Early Childhood A-7	Black Residual Mastic (Under Carpet and 12" Gray Spec Floor Tile)	1240 ft ²	C				
	Black Sink Mastic	2 Units	G				
	Building Caulking	20 lf	G				
	Interior Door Caulking	34 lf	G				
	Piping Fitting Insulation	11 Units	G				
A-6 Nantucket Community	Black Sink Mastic	1 Unit	G				
	Building Caulking	20 lf	G				
	Interior Door Caulking	34 lf	G				
	Piping Fitting Insulation	15 Units	G				
A-5	Black Sink Mastic	2 Units	G				
	Building Caulking	20 lf	G				
	Interior Door Caulking	34 lf	G				
	Piping Fitting Insulation	12 Units	G				
A-4	Black Sink Mastic	2 Units	G				
	Interior Door Caulking	51 lf	G				
	Building Caulking	60 lf	G				
	Piping Fitting Insulation	16 Units	G				

AHERA Six-Month Surveillance Inspection Date: _____ (Name): _____

Signature: _____

Nantucket Elementary School-30 Surfside Rd.

Location	ACM Description	Estimated Quantity	VERTEX 2023 Cond.	Jan. 2024 Cond.	July 2024 Cond.	Jan. 2025 Cond.	July 2025 Cond.
A-3	Black Sink Mastic	2 Units	G				
	Interior Door Caulking	51 lf	G				
	Building Caulking	60 lf	G				
	Piping Fitting Insulation	13 Units	G				
A-2	Black Sink Mastic	1 Unit	G				
	Interior Door Caulking	51 lf	G				
	Building Caulking	60 lf	G				
	Piping Fitting Insulation	4 Units	G				
A-1	Black Sink Mastic	1 Unit	G				
	Interior Door Caulking	51 lf	G				
	Building Caulking	60 lf	G				
	Piping Fitting Insulation	18 Units	G				
B-Cluster Area	12" Beige Floor Tile and Mastic (Black)	1440 ft ²	G				
	Black Sink Mastic	2 Units	G				
	Building Caulking	100 lf	G				
	Interior Door Caulking	119 lf	G				
	Piping Fitting Insulation	8 Units	G				
B-6	Black Sink Mastic	1 Unit	G				
	Interior Door Caulking	51 lf	G				
	Building Caulking	30 lf	G				
	Piping Fitting Insulation	21 Units	G				
B-5	Black Sink Mastic	1 Unit	G				
	Interior Door Caulking	68 lf	G				
	Building Caulking	30 lf	G				
	Piping Fitting Insulation	15 Units	G				

AHERA Six-Month Surveillance Inspection Date: _____ **(Name):** _____

Signature: _____

Nantucket Elementary School-30 Surfside Rd.

Location	ACM Description	Estimated Quantity	VERTEX 2023 Cond.	Jan. 2024 Cond.	July 2024 Cond.	Jan. 2025 Cond.	July 2025 Cond.
B-4	Black Sink Mastic	1 Unit	G				
	Interior Door Caulking	51 lf	G				
	Building Caulking	40 lf	G				
	Piping Fitting Insulation	4 Units	G				
B-3	Black Sink Mastic	1 Unit	G				
	Interior Door Caulking	51 lf	G				
	Building Caulking	40 lf	G				
	Piping Fitting Insulation	18 Units	G				
B-2	Black Sink Mastic	1 Unit	G				
	Interior Door Caulking	34 lf	G				
	Building Caulking	40 lf	G				
	Piping Fitting Insulation	15 Units	G				
B-1	Black Sink Mastic	1 Unit	G				
	Interior Door Caulking	34 lf	G				
	Building Caulking	60 lf	G				
	Piping Fitting Insulation	9 Units	G				
Reading Room	12" Beige Floor Tile and Mastic (Black)	1250 ft ²	G				
	Black Residual Mastic (Under 12" Gray Spec Floor Tile)	250 ft ²	C				
	Interior Door Caulking	51 lf	G				
	Piping Fitting Insulation	8 Units	G				
C-Cluster Area	12" Beige Floor Tile and Mastic (Black)	1860 ft ²	G				
	Black Sink Mastic	1 Unit	G				
	Building Caulking	100 lf	G				
	Interior Door Caulking	119 lf	G				
	Piping Fitting Insulation	7 Units	G				
C-7 Storage	12" Beige Floor Tile and Mastic (Black)	100 ft ²	C				

AHERA Six-Month Surveillance Inspection Date: _____ **(Name):** _____

Signature: _____

Nantucket Elementary School-30 Surfside Rd.

Location	ACM Description	Estimated Quantity	VERTEX 2023 Cond.	Jan. 2024 Cond.	July 2024 Cond.	Jan. 2025 Cond.	July 2025 Cond.
C-6	Black Sink Mastic	1 Unit	G				
	Interior Door Caulking	51 lf	G				
	Building Caulking	30 lf	G				
	Piping Fitting Insulation	15 Units	G				
C-5	Black Sink Mastic	1 Unit	G				
	Interior Door Caulking	51 lf	G				
	Building Caulking	40 lf	G				
	Piping Fitting Insulation	7 Units	G				
C-4	Black Sink Mastic	1 Unit	G				
	Interior Door Caulking	51 lf	G				
	Building Caulking	40 lf	G				
	Piping Fitting Insulation	18 Units	G				
C-3	Black Sink Mastic	1 Unit	G				
	Interior Door Caulking	51 lf	G				
	Building Caulking	40 lf	G				
	Piping Fitting Insulation	4 Units	G				
C-2	Black Sink Mastic	1 Unit	G				
	Interior Door Caulking	51 lf	G				
	Building Caulking	40 lf	G				
	Piping Fitting Insulation	11 Units	G				
C-1	Black Sink Mastic	1 Unit	G				
	Interior Door Caulking	51 lf	G				
	Building Caulking	20 lf	G				
	Piping Fitting Insulation	11 Units	G				

AHERA Six-Month Surveillance Inspection Date: _____ (Name): _____							
Signature: _____							
Nantucket Elementary School-30 Surfside Rd.							
Location	ACM Description	Estimated Quantity	VERTEX 2023 Cond.	Jan. 2024 Cond.	July 2024 Cond.	Jan. 2025 Cond.	July 2025 Cond.
Library Area	Black Sink Mastic	2 Units	G				
	Interior Door Caulking	68 lf	G				
	Building Caulking	30 lf	G				
	Piping Fitting Insulation	6 Units	G				
Library Hall Area	Interior Door Caulking	289 lf	G				
	Building Caulking	120 lf	G				
	Piping Fitting Insulation	53 Units	G				
110	Black Sink Mastic	1 Unit	G				
	Interior Door Caulking	34 lf	G				
	Building Caulking	20 lf	G				

Notes:

- | | | | |
|-------------------------------|-------------------|---------------------------------|---------------------|
| ft ² = Square Foot | Cond. = Condition | U = Unknown | NA = Not Accessible |
| lf = Linear Foot | G = Good | C = Covered | |
| Unit = Each | MD = Minor Damage | M = Miscellaneous | |
| Y= Yes | D = Damaged | S= Surfacing | |
| N = No | Fri. = Friable | TSI = Thermal System Insulation | |

APPENDIX G

SCHEMATICS



TBA ARCHITECTS, INC.
PLANNING
ARCHITECTURE
INTERIOR DESIGN

200 CROSBY STREET, BELLINGHAM, MA 01924
TEL: 978-251-1000 FAX: 978-251-1001

NANTUCKET PUBLIC SCHOOLS
MASTER PLANNING
NANTUCKET, MASSACHUSETTS

REVISIONS

DATE OF ISSUE
JANUARY 08, 2007

SCALE

NTS

EXISTING CONDITIONS
ELEMENTARY SCHOOL
Existing Space Analysis

SHT-1

NOT FOR CONSTRUCTION
TBA PROJECT# 1072

BULK SAMPLE LOCATION = 01A

COLOR LEGEND

- | | |
|----------------------------------------|--------------------------------------|
| CORE ACADEMIC SPACES | ADMINISTRATION & GUIDANCE |
| General Classrooms | Office |
| Kindergarten/Pre-K | Guidance |
| Specialized Classrooms | AUDITORIUM/DRAMA |
| | Auditorium/Stage |
| SPECIAL EDUCATION | CUSTODIAL & MAINTENANCE |
| Special Ed. Spaces | Janitor/Storage |
| ART & MUSIC | MEDICAL |
| Art | Office/Exam |
| Music | |
| HEALTH & PHYSICAL EDUCATION | DINING & FOOD SERVICE |
| Gymnasium | Cafeteria |
| Locker Rooms | Kitchen |
| Office | Stage |
| Storage | Storage |
| MEDIA CENTER (LIBRARY) | VOCATIONS & TECHNOLOGY |
| Media Center | Vocations & Technology |
| CIRCULATION | RESTROOMS |
| Circulation/Common Space | Toilet Rooms |



PROGRESS SET
February 1, 2007